# OREGON CORNER RESTORATION FORM

#### PREVIOUS RENEWALS/SURVEYS ETC.

Originally surveyed by Thompson under Contract #83 in 1859. He set post and made mound.

### MONUMENTS AND ACCESSORIES FOUND: CONDITON AND SOURCE

Found Fence corner.

### MONUMENT DETAIL

T2N R29E 22| 23 27| 26 2008 LS 951

### OREGON STATE PLANE COORDINATES NORTH ZONE, NAD 83(91), Int Feet:

719284.98 8544057.33

## MONUMENT SET (PROCEDURES AND DESCRIPTION)

At a fence corner I set a 2 3/8" brass cap on a 1" x 30" iron pipe at ground level stamped as above.

#### NEW ACCESSORIES FROM WHICH

A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 1° 40' 38" W 42.28' A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 67° 13' 43" E 112.34' A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 0° 22' 48" E 44.24' A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 87° 52' 04" W 37.23' These bearings and distances are State Plane.

#### LOCATION AND COMMENTS

From Cunningham sheep ranch shop go southwesterly on Cunningham Road 2.5 miles to fork. Take left fork South 1 mile to fork. Take right fork South 1.5 mile to fence. Corner is 0.7 mile West.

FIRM: EDWARDS SURVEYING LLC PO BOX 763 - HERMISTON OR 97838

PARTY CHIEF: G. EDWARDS WITNESS: R. SMITH SURVEYOR'S SEAL

PROFESSIONAL LAND SURVEYOR

OREGON JULY16, 1971 G. DENNIS EDWARDS 9 5 1

RENEWS 12/31/11

C:/Works/N5R29-J1

11-63-C