

PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, DATE: 01/24/02

CORNER DESIGNATION: 2N33T25, The East Quarter Corner of Section 25.

PREVIOUS RENEWALS/ SURVEYS, ETC..:

Most recent Umatilla County Surveyors recorded survey record: 94-117-B.

MONUMENT AND ACCESSORIES FOUND:

Found a 2 1/2" brass cap on 2" galvanized iron pipe with top 14" above ground level, approximately 1.5 North of a fence corner, marked as shown in monument marking detail. There are no accessories to this corner. Corner is a C.E. Redfield monument circa 1918.

MONUMENT MARKING DETAIL:

INDIAN ALLOTMENT

1 R33 | R34

4 S25 | S30

T2N R33E

LOCATION & COMMENTS:

Approximately 1.5 feet North of fence corner, fences West and South.


STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

N = 719110.84


E = 8682591.89

FIRM/AGENCY: William R. Wells
P.O. Box 1696
Pendleton, Oregon 97801

2N33T25



William R. Wells



RENEWS 6-30-02

RECEIVED BY

Umatilla County Surveyors

Date 2-02

Rec'd by KK

No. 02-43-9