USDA FOREST SERV	/ICE CORNER RECORD (SEARCH)
File No. T.25-22 T.4S., R.32E. Meridian: Willam	
CORNER DIAGRAM ( 525 )	DESCRIBE CORNER MONUMENT FOUND
C-N-N-SW   1/256   1994   PLS 2405	None. Corner established this survey.
	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
PHOTO ID DATA Photo No. Filed At ! Object ID !	None. Corner established this survey.
PLANE CO-ORD   State Zone   X	
Y Estab.By	DESCRIBE CORNER LOCATION: Corner falls on south slope of Ponderosa Pine.
Signature: Mulflewillle Title: Land Surveyor Date: 10/26/94	

## CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MON. Set  $2-1/2"\times30"$  aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the DIAGRAM, 15" in the ground and raised a mound of earth and stone 3 ft. dia.  $\times$  1½ ft. high. From Which:

ACCESSORIES: DESCRIBE NEW BT'S, W.O.'S ETC. ESTABL./WORK DONE TO PRESERVE Pond. Pine, 14" dia., bears \$54.05'E,79.40 ft., scribed: C-N-N-SW 1/256 \$25 BT Pond. Pine, 8" dia., bears \$04.36'E,34.40 ft., scribed: C-N-N-SW 1/256 \$25 BT Measurements to BT's taken with an Electronic Tacheometer with bearings based on the survey control network. Set steel fence post with Land Survey Monument (54-9) and Property Boundary (54-2) signs 5' south and east of the monument. Nailed a brass washer stamped PLS 2405 on blaze above BT scribe as taken this survey. Nailed Bearing Tree (54-3) signs above blaze and Land Survey Monument (54-9) signs on back of each tree as required. Painted a 6" red band above Bearing Trees signs.

Work Done by: Susan E. Newstetter Or.Land Surveyor No. 2405 Date: 10/26/94 Certified Cor. Record Prepared? X Yes \_\_No Filed At: Umatilla Co. Survey.

REMARKS