CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None. Corner established as part of this survey.

P-11 DIAGRAM T 4 S R 32 E C 1/4 S 21 PLS 1106 1992

Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the

original location of this corner: At position established by survey...

Set a $2\frac{1}{2}$ " X 30" aluminum pipe with $2\frac{1}{2}$ " aluminum cap 10" in ground surrounded with mound of earth and stone set steel fence post next to corner and attached signs 54-2 & 54-9. Cap marked as shown in corner diagram.

- New bearing trees established: A 11" ponderosa pine brs $N60\frac{1}{4}^{0}E$, 97.3' dist mkd C1/4S21 BT. A 17" ponderosa pine brs $N82\frac{1}{4}^{0}E$, 103.1' dist mkd C1/4S21 BT. A 22" ponderosa pine brs $S61^{0}W$, 118.0' dist mkd C1/4S21 BT. A 18" ponderosa pine brs $S77^{0}W$, 111.9' dist mkd C1/4S21 BT.

New BT's have a brass washer stamped PLS 1106 nailed to face of blaze. Attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each BT.

Compass declination 180 East.

I hereby certify that the above corner monument was properly established to U.S.F.S. standards by me on June 11, 1992.

REGISTERED PROFESSIONAL LAND SURVEYOR Will R. Well OREGON JULY 22, 1977 WILLIAM R. WELLS

1106

Office of County Surveyor County of Umatilla for record on the...... day of...... , 19..... (COUNTY OFFICIAL)

Form R6-7100-57 (9/71)

RECEIVED BY

Umatilla County Surveyor

Date

Rec'd By

☆ GPO---798-276