USDA FOREST SERV	VICE CORNER RECORD (SEARCH)	
File No. P-22	R.D.: N.F.J.D. Co. Survey No:	
T.48., R.32E.	N.F.: UMATILLA County: Umatilla	
Meridian: Willam		
CORNER DIAGRAM T48 R32E	DESCRIBE CORNER MONUMENT FOUND	
W1/16 CC	None. Corner established this survey.	
524 1994		
PLS 2405	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOL	JND
PHOTO ID DATA	None. Corner established this survey.	Ì
Photo No. 1		- 1
Filed At		- }
Object ID		(
1		[.
PLANE CO-ORD	to an attachment and the control of	¥
State Zone !	•	-
X I		F
Υ !	DESCRIBE CORNER LOCATION:	È
Estab.By !	Corner falls on east slope of D.Fir and P.Pine. N-S dra bottom is 100' west.E-W fence is 1' south.N-S road 50'ea	ω [st
Signature: (lul	Hewsteller Title: Land Surveyor Date: 10/20/94	

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MON. Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the DIAGRAM, 24" in the ground. From Which:

ACCESSORIES: DESCRIBE NEW BT'S, W.O.'S ETC. ESTABL./WORK DONE TO PRESERVE Douglas Fir, 12" dia., bears N31°05'W, 36.4 ft., scribed: C-W1/16 S24 BT Douglas Fir, 12" dia., bears S49°59'W, 37.4 ft., scribed: C-W1/16 S24 BT Measurements to BT's taken with an Electronic Tacheometer with bearings based on the survey control network. Set steel fence post with Land Survey Monument (54-9) and Property Boundary (54-2) signs 5' north and south of the monument. Nailed a brass washer stamped PLS 2405 on blaze above BT scribe as taken this survey. Nailed Bearing Tree (54-3) signs above blaze and Land Survey Monument (54-9) signs on back of each tree as required. Painted a 6" red band above Bearing Trees signs.

Work Done by: Susan E. Newstetter Or.Land Surveyor No.2405 Date: 10/20/94 Certified Cor. Record Prepared? X Yes No Filed At: Umatilla Co. Survey.

REMARKS