USDA FOREST SERV	ICE CORNER RECORD (SEARCH)
File No. Q-23	R.D.: N.F.J.D. Co. Survey No:
T.48., R.32E.	·
Meridian: Willam	ette
CORNER DIAGRAM T48 R32E	DESCRIBE CORNER MONUMENT FOUND
C !	None. Corner established this survey.
S1/16 S24	
C 1994	
PLS 2405	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
PHOTO ID DATA Photo No. Filed At Object ID	None. Corner established this survey.
PLANE CO-ORD	
State Zone !	
X I	DESCRIBE CORNER LOCATION:
Estab.By	Corner falls on center of an E-W ridgetop of P.Pine and
1	D. Fir.
Signature: (Jul Jewillle) Title: Land Surveyor Date: 10/18/94	

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MON. Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the DIAGRAM, 24" in the ground. From Which:

ACCESSORIES: DESCRIBE NEW BT'S, W.O.'S ETC. ESTABL./WORK DONE TO PRESERVE Douglas Fir, 10" dia., bears \$75°30'E, 83.0 ft., scribed:C-\$1/16 \$24 BT Ponderosa Pine, 10" dia., bears \$24°15'E, 47.7 ft., scribed:C-\$1/16 \$24 BT Measurements to BT's taken with an Electronic Tacheometer with bearings based on the survey control network. Set steel fence post with Land Survey Monument (54-9) and Property Boundary (54-2) signs 5' south and east of the monument. Nailed a brass washer stamped PLS 2405 on blaze above BT scribe as taken this survey. Nailed Bearing Tree (54-3) signs above blaze and Land Survey Monument (54-9) signs on back of each tree as required. Painted a 6" red band above Bearing Trees signs.

Work Done by: Susan E. Newstetter Or.Land Surveyor No. 2405 Date: 10/18/94 Certified Cor. Record Prepared? X Yes __No Filed At: Umatilla Co. Survey.

REMARKS