## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None. Corner established as part of this survey.

L-7	
DIAGRAM T 5 S	R 34 E
T 5 S	K 34 E
C 1/4	s 17
	•
19	993
PLS	1106

Description of corner evidence found:

None.

## Description of monument and accessories I established to perpetuate the original location of this corner

At position established by survey...

Set a 2½ " aluminum cap on 2½ "x30" aluminum pipe 28" in ground surrounded with mound of earth & stone. Set steel fence post 4.0'South of corner & attached sign 54-9 & 54-2.

New bearing trees established: A 19"diam.Western Larch brs. S80°E,135.9' scribed C1/4S17 BT. A 12"diam douglas fir brs S15°W,58.0' scribed C1/4S17 BT. A  $8\frac{1}{2}$ "diam.Western Larch brs. N84°W,48.0' scribed C1/4S17 BT. A 10"diam.Western Larch brs. N46°W,47.1' scribed C1/4S17 BT.

New bearing trees have a brass washer stamped PLS 1106 nailed to face of blaze. Attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each

Compass declination 180 East.

I hereby certify that the above corner was properly established to U.S.F.S. standards by me on October 28, 1993.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 22, 19/7 WILLIAM R. WELLS

1106 Office of County Surveyor County of Ufmatilla -- renews 12-31-94 State of Oregon , I hereby certify that the within instrument was filed in this office 

RECEIVED BY

Umatilla County Surveyor

Data 8-4-94

Form R6-7100-57 (9/66)