## History of original corner establishment:

Corner position established by the Bureau of Land Management during survey performed between 1967 and 1980:

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 15 ins. in ground to bedrock and in a mound of stone 3 ft. base to top, with brass cap mkd.

Raise mound of stone 3 ft. base 2 ft. high S of corner.

T6S R32E 1968

DIAGRAM	
T5S	
6	
1/4 T6S R32E	

## Description of corner evidence found:

Found a 2 1/2" diameter iron pipe with brass cap marked:

Firmly set in a mound of stone as described in the BLM record.

U.S. Dept. of Interior Bureau of Land Management

1/4 S6 **T6S R32E** 1968

Description of monument and accessories I established to perpetuate the original location of this corner:

We establish the following bearing objects: A 5/8"x30" iron rod driven 18" in the ground and supported in a mound of stone, 3 ft. dia. at the base to top of rod, with plastic cap marked "AP & A", bears S45°W 15.0 feet.

And a 5/8"x30" iron rod driven 15" in the ground and supported in a mound of stone, 3 ft. diameter base to top of rod, with plastic cap marked "AP & A" bears S59°E 15.5 feet.

Corner is located 2 ft. north of an E-W fence.

Magnetic Compass (20° East Declination) Steel Tape

September 6, 1984

Witnesses:

Gary Langlitz, LS 1099

Ray Crapo

Greg Orton

REGISTERED **PROFESSIONAL** LAND SURVEYOR

LANGLITZ

, 19.8.9

Kriembein (COUNTY OFFICIAL)

(DEPUTY)

Form R6-7100-57 (9/71)