USDA-FOREST SERVICE GP 0 940-	0-117 The second of the second	
Index File No. A-9	CORNER RECORD (SEARCH) Tract or Cor.  (Ref. FSM 7.151.4) Survey No No.	
T 65 R. 32 E	R.D. UKIAH (Ref. FSM 7.151.4) Survey No No	•
Merid. WILLAMETTE	N.F. UMATILLA State OREGON	
T 5S S32	Found a $2\frac{1}{2}$ " iron pipe, firmly set, with brass cap marked as described in Gaylord Record (refer to Umatilla Co. Surveyor's Record No. 82-102-R), from which:	
5   4 N CC   T6S R32E	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND	
6	The stumps of the original Campbell BT's exist as described in the Gaylord Record, and BT's marked by Gaylord, A 10" Douglas Fir bears S 13°E 73.9 ft. This tree is alive and	i '
PHOTO IDENTIFICATION DATA Photo No. Z80-293 Filed At. UMATILLA NAT. FOR	and in good condition, it does not appear to have been marked as described in the Gaylord Record.  And a 16" Douglas Fir, alive with partially healed blaze bears S 40°W 90.4 links.	
Object Ident. D125cv Ident. By	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER	Annag n
PLANE COORDINATE POSITION DATA		• • • •
State Zone X Y		. :
Estab. By		-
Signature	Title Division Headquarters Date FS-7100-52 (3/68)	

## CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

None

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE We scribe the SE Gaylord BT as follows, scribed "CC T6S R32E S4 BT" on a double blaze, attached a brass washer marked "LS 1099" to lower blaze.

Date 8-84 State Registration No. Work Done By Gary Langlitz Title LS 1099 Certified Con Record, Prepared ? (765) No Filed At: \ REMARKS

M.WILLAMETTE

Tract or Surv. No.

Cor.