CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Original survey by Frank Campbell, under Contract No. 468, dated April 12, 1883.

Set a pine post, 4 ft. long, 4 ins. square, 24 inches in the ground for corner to sec's 4, 5, 8 and 9, marked T6S S4 on NE R33E S9 on SE

S8 on SW S5 on NW DIAGRAM **T6S R33E**

Faces, with 5 notches on S and 4 notches on E edges from which:

A Pine, 24 ins. dia. bears N11°E 41 lks. Dist., marked T6S R33E S4 BT. A Pine, 6 ins. dia. bears S40°E 63 lks. Dist., marked T6S R33E S9 BT.

A Pine, 24 ins. dia. bears S48°W 9 lks. Dist., marked T6S R33E S8 BT.

A Pine, 24 ins. dia. bears N42°W 20 lks. Dist., marked T6S R33E S5 BT.

Description of corner evidence found:

Found the remains of three original bearing trees:

A 24" Ponderosa Pine snag, (orig. SW bearing tree), approx. 20' tall, with scribing "T6S R33E S8 BT" visible on an unhealed double blaze,

A 24" Ponderosa Pine snag, (orig. NW bearing tree), approx. 30 ft. tall, with

scribing "S R33E S5 BT" visible on an unhealed double blaze,
And a 20" Ponderosa Pine, dead and down, with scribing "T6S R33E S4 BT" visible

on an unhealed double blaze.

Also found a steel fence post with BLM location tag near corner location.

No evidence of the original SE bearing tree or the original corner post was found.

Description of monument and accessories I established to perpetuate the

original location of this corner:

The original corner point is determined at record distances from the blazed faces of the remaining original bearing trees.

At the corner point we set a 2"x30" galvanized iron pipe, 26" in the ground, with

brass attached marker: T6S R33E from which:

The original BT's

A 24" Ponderosa Pine snag bears S58°W, 69 ft.

A 24" Ponderosa Pine snag bears N38°W, 142 ft.

A 20" Ponderosa Pine windfall bears N13°E 273 ft. And new bearing trees

S8 S9 PLS 1099 1984

A 12" Western Larch, scribed "T6S R33E S4 BT" on a double blaze, bears N17°E 58.6

A 12" Engleman Spruce, scribed "T6S R33E S9 BT" on a double blaze bears S5°E, 56/

A 14" Douglas Fir, scribed "T6S R33E S8 BT" on a double blaze bears S56°W, 38∠

And an 8" Douglas Fir, scribed "T6S R33E S5 BT" on a double blaze bears N15°W, 18.4 ft.

Attached a brass washer, marked "LS 1099" to face of lower blaze on all new BT's. Reset found steel fence post approx. 5 ft. west of corner and attached U.S.F.S.

"Attention" and "Property Boundary" signs to post. Corner located approx. 5' N. of E-W fence.

Compass Declination: 20°E

Steel tape

August 1, 1984

Witnesses:

Gary Langlitz, LS 1099

Ray Crapo

Greg Orton

County of Private

nereby certify that the within instrument was filed in this office 19.84

D Krumber COUNTY OFFICIAL

Form R6-7100-57 (9/71)

☆ GPO 799-509

GARY L

REGISTERED PROFESSIONAL

AND SURVEYOR

1009

GON

MGLITZ

84-154-R