History of original corner establishment:

R32E S2 BT.

This corner was originally established by Frank Campbell in 1884. The original notes state that at the corner a 18"by15"by8" basalt stone was set 12" in the ground for closing corner for Sections 1 and 2, marked "CC", with one notch on the east and 5 notches on the west edges from which: A 20" tamarack bears S31°E-27 lks (17.8 ft), marked T6S R32E S1 BT.

A 10" pine bears S78°W-141 lks (93.1 ft), marked T6S

DIAGRAM T5S S35 CIC T6S R32E

In 1982, the corner was recovered by LS 1636. The recorded corner certificate states that the corner was reestablished by measurements from original bearing trees, and a 2½" by 30" iron pipe with brass cap was set 20" in the ground with a mound of stone from which: ... See Page 2 ...

Found a 2½" by 30" galv. iron pipe with flared flange and a 2½" brass cap protruding 8" from a stone mound from which:
A 25" pon. pine bears S6 E-46.76' to a nail in the west side of tree, with scribing visible on a partly healed blaze. (1982 bearing tree).
A 19" pon. pine bears S79½ W-93.1' with scribing visible on a partly healed blaze which has been previously opened. (Original bearing tree).
A 12" douglas fir bears S73 W-22.4' with healed blaze. (1982 bearing tree).
A 18" down western larch snag bears S31 E-17.8' to root hole and stump remains with visible scribing under tree. (Original bearing tree). REGISTERED

> PROFESSIONAL LAND SURVEYOR

Wellin R. Wells

Description of monument and accessories I established to perpetuate the original location of this corner:

OREGON JULY 22, 1977 WILLIAM R. WELLS 1106

This corner is likely to be destroyed by a new timber sale road. by 5/8" iron rod to bedrock with a $1\frac{1}{2}$ " aluminum cap marked as shown. Buried monument by LS 1636 horizontally next to the new monument. The top of the new monument is 6" below the rut in the road at the corner point. From the new monument:

A reference monument bears S1320E-145.18', marked RM NW S1 CC 145.18 FT LS 1106 1986. An arrow points toward the corner point.
A reference monument bears S782 W-132.26' marked RM NE S2 CC 132.26 FT LS 1106 1986. An arrow points toward the corner point.

The angle between the two reference monuments, as observed from the corner point is 92°13', measured with a theodolite. Reference monuments are 5/8"by 30" iron rods with 1½" aluminum caps. A 6' steel fence post with sign 54-9 attached is set within one foot of each reference monument.

Painted face of blaze and a 6" red band around each bearing tree. Attached sign 54-3 and 54-9 to each bearing tree.

Used steel tape and staff compass with 19°E declination, measured to the center of the bearing trees.

S2 | S1 CIC T6S R32E LS 1106

T5S S35

Monument cap is

marked:

This corner was remonumented on April 7, 1986.

1986

Office of County Surveyor Cou	unty of Umatilla
State of Qr. eg. on , I hereby certify that the	
for record on the day of	
(COUNTY OFFICIAL)	(DEPUTY)

Form R6-7100-57 (9/71)

RECEIVED BY

Umatilla Courty Surveyof \$u.s. government printing office-1983-793-276

Date 4.25-86 Reo'd by

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Page 2

A-21

DIAGRAM

T5S S35

S2 | S1

T6S R32E

History of original corner establishment:

An 18" pine bears $878^{\circ}W-141$ lks (93.1 ft) with scribe marks visible on a partly healed blaze.

A stump hole with an 18" larch lying alongside bears S 31° E-27 lks (17.8 ft) with scribes "CC" visible.

The following bearing trees are stated on the recorded certificate to have been marked in 1982:

A 10" pine bears S59°E-16½ lks (10.9 ft), scribed T6S R32E S1 CC BT. A 9" fir bears S73°W-34 lks (22.4 ft), scribed T6S R32E S2 CC BT.

Description of corner evidence found:

Description of monument and accessories I established to perpetuate the original location of this corner:

> REGISTERED PROFESSIONAL LAND SURVEYOR

Illi R. Wells OREGON

JULY 22, 1977 WILLIAM R. WELLS 1106

State of ... Oregon, I hereby certify that the within instrument was filed in this office (COUNTY OFFICIAL)

Form R6-7100-57 (9/71)

RECEIVED BY

Umatilla County Surveyor

☆U.S. GOVERNMENT PRINTING OFFICE - 1983-793-276

(DEPUTY)