

Paradise and others March 1910

Chains Links

From the N.E. corner of section 2 T. 4 N. R. 28 E. W. Co. I ran west on true line; 80.44 chs. to section corner.

60.33 Thence east on true line; 20.11 chs. set 4x4 in. post for  $\frac{1}{16}$  section corner; 40.22 chs. set iron pipe for  $\frac{1}{4}$  section corner. set 4x4 in. post for  $\frac{1}{16}$  section corner.

From the  $\frac{1}{4}$  section corner on the north of section 2 I ran south on true line; to the  $\frac{1}{4}$  section corner on the south side of said section 2.

10.06 From the  $\frac{1}{4}$  section corner between sections 2 & 3 of said township and range I ran east on random line; 50.80 chs. intersect 12 links east of  $\frac{1}{4}$  section corner. Thence S.  $89^{\circ} 55' W.$  on true line set  $\frac{1}{4}$  section corner; 20.12 $\frac{1}{2}$  chs. set  $\frac{1}{16}$  section corner.

30.19 set  $\frac{1}{16}$  section corner; 40.25 intersect true north and south line where I set  $\frac{1}{4}$  section corner; 50.31 chs. set  $\frac{1}{16}$  section corner to  $\frac{1}{4}$  section corner.

23.10 From the  $\frac{1}{4}$  section corner T. Secs. 1 & 2 I ran north on true line, 43.34 chs. to section corner. Thence south on true line set  $\frac{1}{16}$  section corner.

10.05 From the  $\frac{1}{16}$  section corner on the east side of the N.E.  $\frac{1}{4}$  of said section 2 I ran west on random line; 60.33 chs. to a point 33 chs. south of  $\frac{1}{16}$  section corner. Thence S.  $89^{\circ} 41' E.$  on true line chs. set  $\frac{1}{16}$  section corner; 20.11 intersect true N & S center line of section where I set  $\frac{1}{16}$  section corner; 30.16 $\frac{1}{2}$  chs. set  $\frac{1}{16}$  section corner

40.22 intersect true N. & S. center line of the N.E.  $\frac{1}{4}$  of said section 2 where I set  $\frac{1}{16}$  section corner; 50.27 $\frac{1}{2}$  chs. set  $\frac{1}{16}$  section corner to  $\frac{1}{16}$  section corner.

60.33

J. W. Kimbrell Co. Surveyor  
by Gary Kimbrell Deputy