

- 2. EXISTING DEVELOPMENT AND PREVIOUS SURVEYS GIVE STRONG EVIDENCE TO THE ORIGINAL PLAT OF THIS SUBDIVISION.
- 3. POINT NO. 13 HAS BEEN SITED AS HAVING QUESTIONABLE STRENGTH BY LOCAL SURVEYOR'S (D. EDWARDS AND I. DRIVER) WHO HAVE PERFORMED SURVEYS WITHIN THIS SUBDIVISION.

CONCLUSION: THE MONUMENTS THAT HAVE BEEN ESTABLISHED AND SET IN THE FIELD TO INDICATE THE PROPERTY CORNERS OF LOTS 17 THRU 24 ARE BASED ON THE EVIDENCE OF BY POINT NO. 1 AND THE EXISTING DEVELOPMENT WITHIN THE SUBDIVISION.

Umatilla County Surveyor

CITY OF HERMISTON

SURVEY FOR:

CITY LIBRARY BUILDING

LOCATION:

LOTS 17 THRU 24 BLOCK 11 OF SUBDIVISION OF LOT "B" OF ORIGINAL TOWN HERMISTON, NW4, SW4, SECTION 11, T.4N., R. 28 E.W.M., CITY OF HERMISTON, UMATILLA COUNTY, OREGON.

DATE:

5/12/88

SCALE: 1" = 100'

• IRON PIN SET

(000) OF RECORD O PK NAIL SET

CITY ENGINEER: PATRICK D. NAPOLITANO, P.E., P.L.S.

SOUTHWEST CORNER OF CURB WALL

(9) NORTHWEST CORNER OF RETAINING WALL

NORTHWEST CORNER OF BUILDING

NORTHEAST CORNER OF BUILDING

BRASS CAP (FOUND) "NW CORNER, NW4, SW4, SECTION 11" - IN VALVE BOX.

NORTHWEST CORNER OF BUILDING