File NoA-9 T3 & 4 S _R32E  MeridW.M.  CORNER DIAGRAM	CORNER RECORD (SEARCH) Tract or Cor. Sec.  (Ref. FSM 7151.4) Survey No. No. Sec.  R.D. Ukiah County Umatilla  N.F. Umatilla State Oregon
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND
S32 S33	Found 19"x10"x6" basalt stone firmly set with 4 notches on east side and 2 notches on west side.
S 5   S 4	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
	A Tamarac 21" in dia. bears N78 <sup>0</sup> E, 13.5 feet. Grown over blaze. A snag 21" in dia. bears N38 <sup>0</sup> W, 65.5 feet. SScribed T3S, R32E S32 BT. 54-3 and old 54-4 on both trees.
PHOTO IDENTIFICATION DATA Photo No Filed At	
Object Identident. By	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
PLANE COORDINATE POSITION DATA State Zone X	Corner is about 1150 ' west of main forest service road going through Granite Meadows.
Estob. By Agency	Title Division Headquarters Date
(2,2,2,1)	Title Division Headquarters Date 7100-52-(3/68) WY P.L.S. 10/26/77

ч

		- 1		10
Work Done By. B.B.	Barbour title	P.L.S.	Date 10/26/7dr Agency	n No. OR PLS 1051
Certified Cor. Record Pre	pared ? Yes No	Filed At:		Date 11
7	*	REMARK	KS	

Placed brass washer stamped PLS 1051 on foot blazes. Painted 6" red band around the

Witnesses to the above corner: D.L. Landers

Index File No.

S. Nelson

BT's and painted blazes red. Placed 54-4 on fence post 3' east of corner.

Tract or Surv. No. Cor.

or.