Index File No. 4S P 32E	CORNER RECORD (SEARCH) Tract or Cor. NW 1/16
т <u>45</u> R. <u>32Е</u>	R.D. Ukiah County Umatilla
Merid. W.M.	_ N.F. <u>Umatilla</u> State <u>Oregon</u>
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND
1	None set.
T4S R32E	
NW - 1/16	
	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
37	None set.
	None Set.
	6
PHOTO IDENTIFICATION DATA	7
Photo No	_
Filed At.	÷ <u> </u>
Object Ident Ident. By	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
Signature	-
PLANE COORDINATE POSITION DATA	Corner falls on a steep west slope in a small opening.
State Zone _	a succep west stope in a small opening.
×	
X	
XY	

CORNER RECORD (PERPETUATION)	GPO 902-673
IONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT	T4S R32E NW1/16 S7
Set 2½"x30" galvanized pipe with brass cap marked:	NW1/16S7
Set pipe 20" in the ground to bedrock and mound of stone around.	OR PLS 1051
	1977
	9
From which: a 20" fir bears $N22^{O}W$, 31.9 feet, scribed $NW1/16$ S7 BT. bears $S03^{O}W$, 30.0 feet, scribed $NW1/16$ S7 BT. Placed brass washer s foot blazes. Placed 54-3s and 54-4s on BT's. Placed 54-2 and 54-4 west and 54-2 and 54-9 on fence post 4' north of corner. Painted 6" BT's and both blazes red.	stamped PLS 1051 on on fence post 4'
Work Done By B.B. Barbour Title P.L.S. Date 11/14/7 State Registration	No. OD DIS 1051
Work Done By. B.B. Barbour Title P.L.S. Date 11/14/7 or Agency	OK FLO 1001

REMARKS

Witnesses to the above: D.L. Landers S. Nelson

Index File No. T.

Certified Cor. Record Prepared ? Yes

R.

. **M.**

Filed At:

Tract or Surv. No.

Cor.

Date

13