Index	CORNER RECORD (SEARCH)  (Ref. FSM 7151.4)  R.D. Ukiah  County  Umatilla  N.E. Umatilla  Oregon
CORNER DIAGRAM	N.F. Ulliactita State Uregon  DESCRIBE CORNER MONUMENT FOUND
N C1/4   S10	None Set.
01/4 010	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND  None Set.
PHOTO IDENTIFICATION DATA Photo No Filed At Object Ident:-	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
Ident. By	The corner lies on a steep southwest slope about 500 ft. southwest of the end of a lightly traveled road.
State Zone Zone Y Zone Agency	
Bevy BBarba	Title Division Headquarters Date 7100-52 (3/68) W7P.L.S. 10/31/77 5

그 맛이 있는 그를 하는 것이 됐다.	CORNER RECORD (PERPETUATION)	GPO 902-67
MONUMENT: DESCRIBE NEW MONUM	ENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMEN	T4S R32E
At surveyed point: Set 2	2½"x30" galvanized pipe with brass cap m	arked: C1/4 S10
		197 <sup>†</sup> OR PLS 1051
mound of stones to cap.	Attached 54-3 and 54-4 signs to both bear	aing twooc Attached
brass washer, stamped PLS	1051, to the foot blaze of both BT's. F I's red. Set painted metal fence post 3	Painted 6 inch band
brass washer, stamped PLS and the blazes on both Bl	1051, to the foot blaze of both BT's. FI's red. Set painted metal fence post 3 attached.	Painted 6 inch band ft. north of corner
brass washer, stamped PLS and the blazes on both Bl with 54-4 and 54-9 signs	1051, to the foot blaze of both BT's. It's red. Set painted metal fence post 3 attached.  Title Party Chief Dote 10/31/775101e Record Agency	Painted 6 inch band ft. north of corner
brass washer, stamped PLS and the blazes on both Bl with 54-4 and 54-9 signs  Work Done By R.C. Orton	1051, to the foot blaze of both BT's. It's red. Set painted metal fence post 3 attached.  Title Party Chief Dote 10/31/775101e Record Agency	Painted 6 inch band ft. north of corner

Index File No. T.

R.

Tract or Surv. No.

Cor.

13