## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

## History of original corner establishment:

Corner originally established by George S.Pershin, U.S. Deputy Surveyor, under Contract No.390, dated May 12,1881. Surveyor General records state: Set basalt stone 14x12x4 on West slope of ridge for cor.to Sec.9,10,15 & 16. A fir 5 in.di.brs. N14°E,45 lks.dis. A pine 7 in.di.brs. S45°E,34 lks.dis. A pine 7 in.di.brs. S7°W, 46 lks.dis. A fir 7 in.di.brs. N45°W, 52 lks

DIAGRAN	1
r4s	R 32 E
S 9	S 10
S 16	S 15
19	77

Corner remonumented by Craig L. Wanless, BLM Cadastral Surveyor

under instructions dated July 18,1977. His record states: The cor. of secs. 9,10,15 & 16, monumented with the original unmarked basalt stone 14x12x4 ins., loosely set 1 in.in the groun from which the remains of the original bearing trees: A pine 22 ins.diam., bears 87 W,46 lks. dist., with scribe marks T4SR visible on partially healed blaze. A fir 21 ins.diam., bears N26 52 lks.dist., with healed blaze. (record N45 W). At the corner point... Set iron post, 28 ins. long,  $2\frac{1}{2}$  ins.diam., 22 ins. in ground with brass cap mkd. (as shown in corner diagram) from which new bearing trees... A fir 13 ins.diam.bears N77 E,59 lks.dist., mkd. T4SR32ES10 BT. RESERVENCE COUNTY A fir 20 ins.diam.bears S34 E,63 $\frac{1}{2}$  lks.dist., mkd. T4SR32ES15 BT Deposit corner stone alongside iron post.

## Description of corner evidence found:

Found  $2\frac{1}{2}$ " iron pipe with  $3\frac{1}{4}$ " brass cap (as shown in corner diagram) no stone available.

- A 23" ponderosa pine brs S3<sup>O</sup>W, 31.1' with scribing visible. A 20" dead white fir brs S34 3/4°E, 41.5' with scribing visible. A 13" dead white fir brs N77½°E, 38.6' with scribing visible. A 24" dead white fir brs N26°W,34.6' with healed blaze.

## Description of monument and accessories I established to perpetuate the original location of this corner:

Set steel fence post next to corner with sign 54-9 & 54-2 attached.

New bearing trees established:

- A 17" ponderosa pine brs N35¼ W, 327.1' scribed T4SR32ES9 BT. A 13" western larch brs N41 E,25.0' scribed T4SR32ES10 BT. A 23" ponderosa pine brs S77¼ E, 94.5' scribed T4SR32ES15 BT.

New BT's have a brass washer stamped PLS 1106 nailed to face of blaze. Attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each BT.

Compass declination 180 East.

I hereby certify that the above corner monument was properly maintained to U.S.F.S. standards by me on June 03, 1992.

> REGISTERED PROFESSIONAL LAND SURVEYOR Well: R. Well OREGON JULY 22, 1977 WILLIAM R. WELLS 1106

Office of County Surveyor State of Oregon , / hereby cer	County of Umatilla	
for record on the day of		
(COUNTY OFFICIAL)	by(DEPUTY)	
Form R6-7100-57 (9/71)	RECEIVED BY Umatilla County Surveyor	ф gPO—798-276
	Rec'd By	7-13
	No 92:80- R	,