USDA-FOREST SERVICE Index File NoL-17 T4S R32E MeridW.M.	CORNER RECORD (SEARCH) Tract or Cor. 1/4 R.D. Ukiah County Umatilla N.F. Umatilla State Oregon
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND
1/4 N S15 • S14	Found 14"x13"x8" Basalt Stone in small mound, clearly marked 1/4 on west side.
1	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
	A Pine 22" in diameter bears S66½°W 40.8 feet, scribed 1/4S BT. A Pine 28" in diameter bears N56°E 39.5 feet. Blaze grown over.
PHOTO IDENTIFICATION DATA	
Photo No.	
Filed At.	
Object Ident	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
Ident. By	
PLANE COORDINATE POSITION DATA	Corner is on steep west slope.on the west edge of small clearing.
State Zone	augu or small clearing.
X	
Υ	
Estob. By	
Agency 8	
ovy B Barbour	Title Division Headquarters Date 7100-52 (3/68) 2 PLS 10/25/77

CORNER RECORD (PERPETUA	GPO 902-6	37 8
MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MO		
Set 2½" x 30" galvanized pipe with brass cap marked:	S15 T S14	
Set pipe 24" in the ground with mound of stone	313 314	
around. Placed corner stone at base of pipe.	OR PLS 1051	
	1977	9
New BT. A fir 18" in diameter bears N20 ^o s, 18.0 feet, scr 54-3's and 54-4's on bearing trees. Painted 6" red band a on new B.T. Placed brass washer stamped PLS 1051 on foot	nd both blazes red	
Placed 54-4 on fence post 4' east of corner.		

Work Done By B.B. Barbour Title_	P.L.S.	Date 10/25/77 State Registration No.	OR PLS 1051
Certified Cor. Record Prepared ? Yes No	Filed At:	Date	- 11
	REMARKS		

Witness to the above corner: D.L. Landers S. Nelson

Index File No. T. R.

M.

Tract or Surv. No.

Cor.

13