USDA-FOREST SERVICE Index File No. M-7 TR32E	R.DUkiah	RECORD (	SEARCH) 51.4) County	Tract or Survey No. Umatilla	Cor. CS1/16
Merid. W.M.	N.FUmati	11a	State	0regon	
CORNER DIAGRAM	DESCRIBE CORNE	R MONUMEN			
C S1/16 S17	None Set.				
C C	DESCRIBE BEARING	TREES OR	OTHER OFFIC	CIAL ACCESSORIES FOL	JND 2
	None Set.				
PHOTO IDENTIFICATION DATA Photo No Filed At					
Object Ident	DESCRIBE CORNER	LOCATION R	ELATIVE TO	NEAR-BY FEATURES, A	LSO HOW TO REACH CORNER
PLANE COORDINATE POSITION DATA State Zone XY	Corner fa	ills abou	t 5 feet	south of a fenc	e in thick timber.
Estab. By Agency	Title	Division	Headq	uarfers: D	ate 7100-52 (3/68)
avy 40 40 arlow	P.L.Ş.			11/	4/77 , 100 02 (3,03) 5

## CORNER RECORD (PERPETUATION) MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT Set 2½"x30" galvanized pipe with brass cap marked: Set pipe 18" in the ground to bedrock with mound of stone around to cap. OR PLS 1051 1977 9 ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A Fir 12" in dia. bears S26°E, 10.9', scribed S1/16 S17 BT. A Fir 12" in dia. bears S52°W, 16.6', scribed S1/16 S17 BT. Placed 54-3, 54-4 and brass washer stamped PLS 1051 on BT blaze. Painted both blazes red and red band around BTs. Placed 54-2, 54-4 and 54-9 on fence posts 3' west and 3' north of corner.

			10
Work Done By B.B. Barbour Title	P.L.S.	Date 11/4/77 State Registration No.	OR PLS 1051
Certified Cor. Record Prepared ? Yes No	Filed At:	Date	11_
	REMARKS		

Witnesses: D.L. Landers

S. Nelson

\_\_\_

Index File No. T. R.

M.

Tract or Surv. No.

Cor.

13