USDA FOREST SERV	VICE CORNER RECORD (SEARCH)
File No. N-19 T.4S., R.32E. Meridian: Willan	N.F.: UMATILLA County: Umatilla
CORNER DIAGRAM ( T4S R32E   S14   1/4   S23   1977	DESCRIBE CORNER MONUMENT FOUND Found an iron monument, extending approx. 6" from the ground, with a brass cap marked as shown in diagram. The monument is solid and in good shape.
(BLM Cap) PHOTO ID DATA Photo No. Filed At Object ID	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND  White Fir snag, 28" dia., with scribing visible, bears S37°12'W, 30.6 ft. This is the original BT. (Rec: S40°W, 31.02 ft.)  White Fir snag, 16" dia., with scribing visible, bears N53°36'E, 36.9 ft. (BLM Rec: N54°E, 37.95 ft.)
PLANE CO-ORD   State Zone   X   Y	DESCRIBE CORNER LOCATION:
Estab.By   Corner falls in the center of a N-S streambed.   Signature   Title: Land Surveyor Date: 10/17/94	
4	

USDA FOREST SERVICE

## CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MON. No work is needed on the monument.

From Which:

ACCESSORIES: DESCRIBE NEW BT'S, W.O.'S ETC. ESTABL./WORK DONE TO PRESERVE Western Larch, 12" dia., bears N75°00'W, 53.3 ft., scribed: 1/4 S14 BT Spruce, 24" dia., bears N85°45'E, 68.9 ft., scribed: 1/4 S14 BT Douglas Fir, 16" dia., bears S61°15'E, 27.4 ft., scribed: 1/4 S23 BT Western Larch, 20" dia., bears S80°15'W, 80.3 ft., scribed: 1/4 S23 BT Measurements to BT's taken with a magnetic compass, declination 20° East, and a nylon clad steel tape. Set steel fence post with Land Survey Monument (54-9) and Property Boundary (54-2) signs 5' east and west of the monument. Nailed a brass washer stamped PLS 2405 on blaze above BT scribe as taken this survey. Nailed Bearing Tree (54-3) signs above blaze and Land Survey Monument (54-9) signs on back of each tree as required. Painted a 6" red band above Bearing Trees signs.

Work Done by: Susan E. Newstetter Or.Land Surveyor No. 2405 Date: 10/17/94 Certified Cor. Record Prepared? X Yes \_\_No Filed At: Umatilla Co. Survey.

REMARKS