INDEX No. T.25-22

History of original corner establishment:

None. Corner established this survey.

DIAGRAM S25 C-N-N-SW 1/256 1994 PLS 2405

Description of Corner Evidence Found:

None. Corner established this survey.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the DIAGRAM, 15" in the ground and raised a mound of earth and stone 3 ft. dia. x 1½ ft. high.

From Which:

Pond. Pine, 14" dia., bears S54°05'E,79.40 ft., scribed:C-N-N-SW 1/256 S25 BT Pond. Pine, 8" dia., bears S04°36'E,34.40 ft., scribed:C-N-N-SW 1/256 S25 BT

Measurements to BT's taken with an Electronic Tacheometer with bearings based on the survey control network. Set steel fence post with Land Survey Monument (54-9) and Property Boundary (54-2) signs 5' south and east of the monument. Nailed a brass washer stamped PLS 2405 on blaze above BT scribe as taken this survey. Nailed Bearing Tree (54-3) signs above blaze and Land Survey Monument (54-9) signs on back of each tree as required. Painted a 6" red band above Bearing Trees signs.

REGISTERED PROFESSIONAL LAND SURVEYOR OREGON JULY 26, 1889 SUSAN E. NEWSTETTER 2405 Renewal Date: 12/31/96	This work was performed by: Susan E. Newstetter PLS 2405 Witnessed by: Rick Saul and Rick Pewonka October 26, 1994 Umatilla County Surveyor Date -95 Hec'd by KK
	County of ertify that the within instrument was record on theday of,19
(COUNTY OFFICIAL)	DEPUTY)