INDEX No. 0-20

History of original corner establishment:

None. Corner established this survey.

DIAGRAM T4S R32E NE 1/16 • \$23 1994

PLS 2405

Description of Corner Evidence Found:

None. Corner established this survey.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the DIAGRAM, 24" in the ground.

From Which:

Ponderosa Pine, 12" dia., bears S36°45'W, 28.1 ft., scribed: NE 1/16 S23 BT Ponderosa Pine, 11" dia., bears NO4°30'E, 19.5 ft., scribed: NE 1/16 S23 BT

Measurements to BT's taken with a magnetic compass, declination 20° East, and a nylon clad steel tape. Set steel fence post with Land Survey Monument (54-9) and Property Boundary (54-2) signs 5' east of the monument and a steel post 5' south with Property Boundary (54-2) sign. Nailed a brass washer stamped PLS 2405 on blaze above BT scribe as taken this survey. Nailed Bearing Tree (54-3) signs above blaze and Land Survey Monument (54-9) signs on back of each tree as required. Painted a 6" red band above Bearing Trees signs.

	REGISTERED PROFESSIONAL LAND SURVEYOR	
Š <u>i</u>	wan Effewelette	て
	OREGON JULY 26, 1099 SUSAN E. NEWSTETTER 2405	
Re	newal Date: 12/3	196

This work was performed by: Susan E. Newstetter PLS 2405 Witnessed by: Rick Saul and

Rick Pewonka

October 17, 1994

RECEIVED BY

Umaiilla Cousty Surveyon
Date 1-95
Roc'd Dy 5K
No. 95-15-B

Office of		County of		0-20
State of filed in this	_I hereby certify office for record	that the within	instrument was	
(COUNT	Y OFFICIAL)	(DEP	UTY)	7