INDEX No. 0-22

History of original corner establishment:

None. Corner established this survey.

Description of Corner Evidence Found:

None. Corner established this survey.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the DIAGRAM, 22" in the ground and raised a mound of stone and earth around the monument.

From which:

Ponderosa Pine, 14" dia., bears N79°01'E, 45.3 ft., scribed: NW 1/16 S24 BT Douglas Fir, 12" dia., bears S26°22'W, 19.9 ft., scribed: NW 1/16 S24 BT

Measurements to BT's taken with an Electronic Tacheometer with bearings based on the survey control network. Set steel fence post with Land Survey Monument (54-9) and Property Boundary (54-2) signs 5' south and east of the monument. Nailed a brass washer stamped PLS 2405 on blaze above BT scribe as taken this survey. Nailed Bearing Tree (54-3) signs above blaze and Land Survey Monument (54-9) signs on back of each tree as required. Painted a 6" red band above Bearing Trees signs.

REGISTERED PROFESSIONAL LAND SURVEYOR

SUSAN E. NEWSTETTER

Dane

Renewal Date: 14/31/96

This work was performed by: Susan E. Newstetter PLS 2405 Witnessed by: Rick Saul and Rick Pewonka October 20, 1994

RECEIVED BY

Umatilia County Surveyor

Date /-95

Bac'd By //

No. 95-15-B

Office			County of	0-2-
State filed	of in this	I hereby cer office for re	tify that the within instrument was ecord on theday of,19	
	(COUNTY	OFFICIAL)	(DEPUTY)	