USDA-FOREST SERVICE	
Index File No. P-11	CORNER RECORD (SEARCH) Tract or Cor. (Ref. FSM 7151.4) Survey NoNo
T <u>4 S</u> R. <u>32 E</u>	R.D. <u>Ukiah</u> County <u>Umatilla</u>
Merid. Willamette	N.F. Umatilla State Oregon
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND
T 4 S R 32 E	<b>1</b>
C 1/4	None. Corner established as part of this survey.
s 21	
PLS 1106	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
1992	None.
PHOTO IDENTIFICATION DATA Photo No. Filed At. Object Ident.	
Ident. By	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
PLANE COORDINATE POSITION DATA	Corner falls in open, on Southwesterly slope, posted line E & W.
State         Zone           X	
Will-Rakles	Title Division Headquarters Date FS-7100-52 (3/68) Land Surveyor Pendleton, Ore. 6-11-92

## CORNER RECORD (PERPETUATION) MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT At position established by survey... Set a $2\frac{1}{2}$ " X 30" aluminum pipe with $2\frac{1}{2}$ " aluminum cap 10" in ground surrounded with mound of earth and stone set steel fence post next to corner and attached signs 54-2 & 54-9. Cap marked as shown in corner diagram. Compass declination 18° East. ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE New bearing trees established: A 11" ponderosa pine brs N60½°E, 97.3' dist mkd C1/4S21 BT. A 17" ponderosa pine brs N821°E, 103.1' dist mkd C1/4S21 BT. A 22" ponderosa pine brs S61°W, 118.0' dist mkd C1/4S21 BT. A 18" porderosa pine brs S77°W, 111.9' dist mkd C1/4S21 BT. New BT's have a brass washer stamped PLS 1106 nailed to face of blaze. Attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each BT.

Work Done By W.R. Wells \_\_\_\_ title Land Surveyor \_\_\_\_ Dote6-11-92 State Registration No. ORLS 1106 Certified Cor. Record Prepared ? Yes XMX Filed At Umatilla County Surveyor

REMARKS

12 13

Cor.

Tract or Surv. No.