INDEX No. P-18

History of original corner establishment:

None. Corner established this survey.

DIAGRAM T4S R32E W1/16 C----C S23 1994 PLS 2405

Description of Corner Evidence Found:

None. Corner established this survey.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the DIAGRAM, 12" in the ground and raised a mound of stone and earth 3½ ft. dia. x 1½ ft. high.

From which:

Ponderosa Pine, 8" dia., bears N59°36'W, 53.6 ft., scribed: C-W1/16 S23 BT Ponderosa Pine, 8" dia., bears S89°24'E, 13.2 ft., scribed: C-W1/16 S23 BT

Measurements to BT's taken with an Electronic Tacheometer with bearings based on the survey control network. Set steel fence post with Land Survey Monument (54-9) and Property Boundary (54-2) signs 5' south and east of the monument. Nailed a brass washer stamped PLS 2405 on blaze above BT scribe as taken this survey. Nailed Bearing Tree (54-3) signs above blaze and Land Survey Monument (54-9) signs on back of each tree as required. Painted a 6" red band above Bearing Trees signs.

REGISTERED PROFESSIONAL LAND SURVEYOR

JULY 26, 1988 SUSAN E. NEWSTETTER

2406

This work was performed by: Susan E. Newstetter PLS 2405 Witnessed by: Rick Saul and

Rick Pewonka November 3, 1994

RECLIVED BY
Umanilla County Surveyor
Data 1-95
Bao'd By KK

(COUNTY OFFICIAL)

(DEPUTY)