INDEX No. P-24

History of original corner establishment:

None. Corner established this survey.

DIAGRAM T4S R32E E1/16 C----C S24 1994 PLS 2405

Description of Corner Evidence Found:

None. Corner established this survey.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the DIAGRAM, 26" in the ground.

From Which:

Douglas Fir, 20" dia., bears N37°29'E, 69.1 ft., scribed: C-E1/16 S24 BT Douglas Fir, 26" dia., bears S72°07'E, 43.7 ft., scribed: C-E1/16 S24 BT

Measurements to BT's taken with an Electronic Tacheometer with bearings based on the survey control network. Set steel fence post with Land Survey Monument (54-9) and Property Boundary (54-2) signs 5' north and south of the monument. Nailed a brass washer stamped PLS 2405 on blaze above BT scribe as taken this survey. Nailed Bearing Tree (54-3) signs above blaze and Land Survey Monument (54-9) signs on back of each tree as required. Painted a 6" red band above Bearing Trees signs.

REGISTEI PROFESSIO LAND SURV	ONAL
OREGON JULY 28, 1981 SUSAN E. NEWST	weteller
Renewal Porte	,

This work was performed by: Susan E. Newstetter PLS 2405 Witnessed by: Rick Saul and Rick Pewonka

October 20, 1994

RECEIVED BY

Umani			
Date_		95	
Rec'd l	By X	K	
No. 9		-0	

Office	of			Co	unty of		r
			for record			instrumen	t was 19
	(COUNTY	OFFICI			(DEP	UTY)	