CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner originally established by George S.Pershin, U.S.Deputy Surveyor, under Contract No.390, dated May 12, 1881. Surveyor General records state: Set basalt stone 14x12x4 on slight N.W.slope for ½ Sec.cor. A pine 9 in.di.brs. N68°E,44 ½ks.dist. A pine 10 in.di.brs. S83°W, 108 ½ks. dist. Corner remonumented by Craig L.Wanless, BLM Cadastral Surveyor under instructions, dated July 18, 1977.

| DIAGRAM | T 4 S R 32 E | 1977

The $\frac{1}{4}$ sec.cor.of secs.21 and 28, monumented with the original unmarked basalt stone 14X12X4 ins., loosely set in a mound of stone, 2 ft.high, from which an original bearing tree: A twin pine 18 ins.diam. brs S83 $^{\circ}$ W,108 lks.dist. with scribe marks $\frac{1}{4}$ S visible on open and burned blaze. At the corner point...Set an iron post,28 ins.long,2 $\frac{1}{2}$ ins.diam.24 ins.in ground with brass cap mkd (as shown in corner diagram) from which new bearing trees: A lodgepole pine 11 ins.diam.brs N $\frac{1}{2}$ E, 23 $\frac{1}{2}$ lks.dist.mkd $\frac{1}{4}$ S21 BT. A lodgepole pine 11 ins.diam.brs S60 $^{\circ}$ E, 26 $\frac{1}{2}$ lks.dist.mkd $\frac{1}{4}$ S28 BT. Deposit corner stone alongside iron post.

Description of corner evidence found:

Found $2\frac{1}{2}$ " iron post with $3\frac{1}{4}$ " brass cap (marked as shown in corner diagram) in mound of stone. A 13" ponderosa pine brs S61 E,17.6' with visible scribing. A 20" ponderosa pine brs N8 $2\frac{1}{2}$ W,70.5' with visible scribing. A 12" ponderosa pine brs N1 W,15.9' with visible scribing.

Description of monument and accessories I established to perpetuate the original location of this corner:

New bearing tree established: A 13" ponderosa pine brs S17°E, 10.2' scribed 1/4S28 BT.

New bearing tree has a brass washer stamped PLS 1106 nailed to face of blaze. Attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each BT. Set 6' steel fence post next to corner with sign 54-9 & 54-2 attached.

Compass declination 180 East.

I hereby certify that the above corner monument was properly maintained to U.S.F.S. standards by me on June 02, 1992.

PROFESSIONAL LAND SURVEYOR

OREGON
JULY 22, 19:77
WILLIAM R. WELLS
1106

Office of County Surveyor	County of Unatilla
State of Oregon , I hereby certify	that the within instrument was filed in this office
for record on the day of	, 19
(COUNTY OFFICIAL)	y(DEPUTY)

Form R6-7100-57 (9/71)

RECEIVED BY
Umatilla County Surveyor

Date 7-92 Reo'd By R-1