USDA-FOREST SERVICE	
Index File No. <u>R-16</u>	CORNER RECORD (SEARCH) Tract or Cor. (Ref. FSM 7151.4) Survey No
T <u>4 S</u> R. <u>32 E</u>	R.D. <u>Ukiah</u> County <u>Umatilla</u>
Merid. Willamette	N.F. Umatilla State Oregon
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND
T 4 S R 32 E S 22 E 1/16	None. Corner established as part of this survey.
N l c 27	2
S 27	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
1992	Found a Kingua tag and old location
PLS 1106	Found a Kinzua tag and old location poster located near corner. point.
6	
PHOTO IDENTIFICATION DATA	
Photo No	
Filed At.	
Object IdentIdent. By	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
Signature -	
PLANE COORDINATE POSITION DATA	Corner is located in a dirt road running East-West. There
State Zone	is a wood fence post with location poster West of corner monument.
X	
Υ	
Estab. By	· -
Will P. Wells	Title Division Headquarters Date FS-7100-52 (3/68) Land Surveyor Pendleton, Ore. 6-09-92

## CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT At position established by survey...

Set a  $2\frac{1}{2}$ " x 30" aluminum pipe with  $2\frac{1}{2}$ " aluminum cap 8" below road surface. Set steel fence post 9.6' North of corner at edge of road with sign 54-2 and 54-9 attached.

Compass declination 180 East.

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE New bearing trees established:

A 12" western larch brs  $S87\frac{10}{2}$ W, 44.5' scribed El/16S27 BT.

A 7" western larch brs  $N54\frac{1}{2}$ °W, 57.8' scribed El/16S22 BT. New BT's have a brass washer stamped PLS 1106 nailed to face of blaze.

Attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each BT.

Work Done By. W.R. Wells Title Land Surveyor Dote 6-09-9-2 State Registration No. ORLS 1106 Certified Cor Record Prepared ? Yes Filed At: Umatilla County Surveyor XNXX Date REMARKS

Cor.

Tract or Surv. No.