File No. R-19 T.48., R.32E. Meridian: Willar	R.D.: N.F.J.D. N.F.: UMATILLA mette	Co. Survey No: County: Umatilla
	DESCRIBE CORNER MONUMENT FOUND Found iron monument, in a mound cap marked as shown in DIAGRAM. firm.	of stone, with a brass Monument is solid and
(BLM Cap)	DESCRIBE BEARING TREES OR OTHER	
PHOTO ID DATA   Photo No.   Filed At	Ponderosa Pine, 12" dia., with scribing visible, bears DATA   N20°31'E, 29.0 ft. (BLM Rec: N21°E, 29.04 ft.) Tree is alive and well.	
Object ID PLANE CO-ORD State Zone	Ponderosa Pine, 28"dia., with he S19°49'W, 37.4 ft. (Org. Rec: Si alive and well.	ealed blaze, bears 23°W, 40.92) Tree is
Estab.By	DESCRIBE CORNER LOCATION: An old E-W fence is approx. 15 ft. north.	
Signature:	Newslelle Title: Land	Surveyor Date: 10/17/94

USDA FOREST SERVICE CORNER RECORD (SEARCH)

## CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MON. No work is needed on the monument.

From Which:

ACCESSORIES: DESCRIBE NEW BT'S, W.O.'S ETC. ESTABL./WORK DONE TO PRESERVE Douglas Fir, 12" dia., bears S27°45'E, 23.8 ft., scribed: 1/4 S26 BT 5/8" x 30" rebar, set in a mound of stone, with yellow plastic cap marked PLS 2405 bears N40°30'W. 7.9 ft.

Measurements to BT and rebar taken with a magnetic compass, declination 20° East, and a nylon clad steel tape. Set steel fence post with Land Survey Monument (54-9) and Property Boundary (54-2) signs 5' north and south of the monument. Nailed a brass washer stamped PLS 2405 on blaze above BT scribe as taken this survey. Nailed Bearing Tree (54-3) signs above blaze and Land Survey Monument (54-9) signs on back of each tree as required. Painted a 6" red band above Bearing Trees signs.

Work Done by: Susan E. Newstetter Or.Land Surveyor No. 2405 Date: 10/17/94 Certified Cor. Record Prepared? X Yes No Filed At: Umatilla Co. Survey.

REMARKS

Index File No. R-19 T.4S., R.32E., W.M.