INDEX No. T-19

History of original corner establishment:

None. Corner established this survey.

DIAGRAM T4S R32E C1/4 • S26 1994 PLS 2405

Description of Corner Evidence Found:

None. Corner established this survey.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the DIAGRAM, 26" in the ground.

From Which:

Ponderosa Pine, 10" dia., bears N70°22'E, 66.0 ft., scribed: C1/4 S26 BT Ponderosa Pine, 9" dia., bears S66°56'E, 34.1 ft., scribed: C1/4 S26 BT Ponderosa Pine, 9" dia., bears S04°07'W, 67.8 ft., scribed: C1/4 S26 BT Ponderosa Pine, 14" dia., bears S59°36'W, 42.1 ft., scribed: C1/4 S26 BT

Measurements to BT's taken with an Electronic Tacheometer with bearings based on the survey control network. Set steel fence post with Land Survey Monument (54-9) sign 5' north of the monument. Nailed a brass washer stamped PLS 2405 on blaze above BT scribe as taken this survey. Nailed Bearing Tree (54-3) signs above blaze and Land Survey Monument (54-9) signs on back of each tree as required. Painted a 6" red band above Bearing Trees signs.

REGISTERED PROFESSIONAL LAND SURVEYOR	This work was performed Susan E. Newstetter PLS — Witnessed by: Rick Saul Rick Pewonka	3 2405
OREGON JULY 26, 1990	→ November 2, 1994	RECEIVED BY
SUSAN E. NEWSTETTER	°C	matilla County Surveyor
Post	D	els 1-95
Renewal Date: 12/31/96		oc'd By
	N	0
Office of	County of	T-19
	certify that the within i	

by

(DEPUTY)

(COUNTY OFFICIAL)