INDEX No. T-23

History of original corner establishment:

None. Corner established this survey.

DIAGRAM T4S R32E C1/4 • S25 1994 PLS 2405

Description of Corner Evidence Found:

None. Corner established this survey.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the DIAGRAM, 26" in the ground.

From Which:

Lodgepole pine, 9" dia., bears N52°15'W, 36.9 ft., scribed: C1/4 S25 BT Western Larch, 20" dia., bears S71°30'E, 72.7 ft., scribed: C1/4 S25 BT 5/8"x30" rebar, set 28" in ground, with yellow plastic cap marked PLS 2405 bears:

N38°30'E, 6.5 ft. (1 groove on rebar) S37°45'W, 9.7 ft. (no groove on rebar)

Measurements to BT's and rebar taken with a magnetic compass, declination 20° East, and a nylon clad steel tape. Set steel fence post with Land Survey Monument (54-9) and Property Boundary (54-2) signs 5' north and east of the monument. Nailed a brass washer stamped PLS 2405 on blaze above BT scribe as taken this survey. Nailed Bearing Tree (54-3) signs above blaze and Land Survey Monument (54-9) signs on back of each tree as required. Painted a 6" red band above Bearing Trees signs.

REGISTERED PROFESSIONAL LAND SURVEYOR	This work was performed by: Susan E. Newstetter PLS 2405 Witnessed by: Rick Saul and Rick Pewonka October 24, 1994
OREGON JULY 28, 1989 SUSAN E. NEWSTETTER 2405 Renewal Date: 12/3/9	Omntilla County Surveyor Date 1-95 Rec'd By KA No. 95-15-B
Office ofI hereby of filed in this office for	County of
(COUNTY OFFICIAL)	(DEPUTY)