## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

The corner was originally established by George S. Pershin under Contract No. 390 dated May 12, 1881. The original notes state that a 5" square wood post was set in a mound of stones for corner. No bearing trees were available.

T4S	T4S
R32E	R33E
536	S31
SI	S6
T5S R32E	T5S R33E

No record of subsequent remonumentation found in County Records .

None. Corner was re-established by double proportion measure.

Description of monument and accessories I established to perpetuate the original location of this corner

At the corner position a 2 inch by 30 inch iron pipe, with brass cap marked as shown, was set 10 inches in the ground and surrounded with a mound of stones. Set steel fence post north and east of corner and attached 54-2 to both posts & 54-4 to one post.

No BT's available. Set 4 reference monuments. Reference monuments are 2"x30" galvanized iron pipes with brass caps set 10" in ground with a mound of stones around them. Set fence post and attached sign 54-4 near each reference monument.

From the corner:	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
		5 R33E @ T55 R32E
2) A R.M. bears N17½° E 21.81 ft. marked:	RM SM	SI SI
<b></b>	1979 (278) 19	79.
.,	PLSIION PLSIION PL	51106 1979
Used steel tape and magnetic comoass with 1	192° east declination. Measure	ed to center of R.M.'s
See map of survey This corner set July 26, 1979	PROFESSIONAL LAND SURVEYOR	T4S R32E   R33E
Witnesses: Greg Flowers, L.S.I.T.  Brent Reynolds	William R. Wells	S36 S31
	OREGON JULY 22, 19/7 WILLIAM R. WELLS 1106	R32F T5S R33E
Office of County Surveyor	County of Umatilla	
State of Oregon , I hereby certify th	of the within instrument was filed in thi	s office
for record on the day of	······································	
(COUNTY OFFICIAL)	(DEPUTY)	

RECEIVED BY

Umatilla County Surveyor

Date August 20,

Rec'd By M. Bughes

No. Q-1134-B coresponding drawming

Form R6-7100-57 (9/71)