OREGON CORNER RESTORATION FORM

COUNTY: Umatilla DATE: 04/01/04

CORNER DESIGNATION: V-15, The North One-Quarter Corner of Section 34, T5N., R33E., W.M.

PREVIOUS RENEWALS/SURVEYS ETC.: Corner originally established by William H. Odell and William L. Lewis, U.S. Deputy Surveyors under Contract No. 110, dated February 7, 1865. Record states: Set 1/4 Sec. post. Drove charred stake; dug pits and raised mound as per instructions.

MONUMENT AND ACCESSORIES FOUND: None. Corner position was reestablished at extended intersection of field lines/berms extending South and East, Confirmed reestablished corner position against record tie from 1888 Northern Pacific Railroad Map. (See accompanying plat).

MONUMENT MARKING DETAIL:

T5N R33E

1/4 S27

S34

2004

PLS 1106

MONUMENT SET: At position determined as described, set a 2 1/2" brass cap (marked as shown in "Monument Marking Detail"), on a 1 1/4" x 30" galvanized iron pipe, 30" in the ground and surrounded with earth.

New accessories to corner monument:

A 5/8" x 30" iron rebar with yellow plastic cap marked "OR PLS 1106, WA PLS 17372", set flush with ground level bears N 34° E, 39.1 feet.

A 5/8" x 30" iron rebar with yellow plastic cap marked "OR PLS 1106, WA PLS 17372", set flush with ground level bears East, 37.2 feet.

A 5/8" x 30" iron rebar with yellow plastic cap marked "OR PLS 1106, WA PLS 17372", set flush with ground level bears S 10° W, 39.3 feet. A 5/8" x 30" iron rebar with yellow plastic cap marked "OR PLS 1106, WA PLS 17372", set

flush with ground level bears N 40° W, 38.6 feet. Attached bearing object signs to rebar accessories. Set steel fence post with witness sign attached, 1 foot North of the corner monument.

LOCATION AND COMMENTS: Corner is located in an un-farmed field corner, with farmed field lines extending South and East. Found old down locust fence post and several down wood fence posts nearby.

FIRM: William R. Wells, PLS

P.O. Box 1696

Pendleton, OR 97801

COMPASS DECLINATION: 18° East

Surveyor's Seal

REGISTERED PROFESSIONAL LAND SURVEYOR

Witnesses: Jason Wells, LSIT

Mark Hammersla

RECEIVED BY

Umatilla County Surveyor

WILLIAM R. WELLS 1106

OREGON JULY 22, 1977

enews 6-30-04

\5N33V15