CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Corner established in 1883 by F. W. Campbell under General Land Office Contract No. 468.

Surveyor General Record States:

Set post for cor. to Sect's. 2-3-10-11, From which:

A 12" Tamarack bears N 61 E, 61 1ks.

A 24" Tamarack bears S 47 W, 29 lks. A 20" Tamarack bears N 40 W, 37 lks.

A 12" Fir bears S 50 E, 10 1ks.

DIAGRAM T.5 S. R.30 E. S 3 |S 2 S 10 S 11

No record of subsequent remonumentation was found in County Records.

Description of corner evidence found:

Found original BTs as follows:

A 8" Tamarack snag bears N29E, 40.0 ft., scribes visable.

A 17" Fir snag bears S75E, 6.6 ft., blaze healed.

A 30" Tamarack, good condition, bears S28W, 22.7 ft., scribes visable. A 32" Tamarack, good condition, bears N53W, 24.4 ft., scribes visable.

Description of monument and accessories I established to perpetuate the

At corner point, based on record distance to BTs, I set $2\frac{1}{2}$ "x30" iron pipe with brass cap marked as shown, 24" in ground, from which:

New BTs

A 13" Fir bears N41E, 67.0 ft. marked T5S R30E S2 BT. A 12" Fir bears S59E, 68.5 ft. marked T5S R30E S11 BT.

Nailed brass washer to BT blaze,

Set steel fence post 5+ ft. South and 5+ East of corner. Corner is approximately 6 ft. South of small creek. Used steel tape and magnetic compasswith 20° E declination.

Measured to face of blaze of original BTs and center of new BTs.

REGISTERED PROFESSIONAL LAND SURVEYOR OREGONY DUANE L GRIFFITH

5S R 30E S 2 S 10 S 11 1974 PLS 644

State of Cold Jak ... I hereby certify that the within instrument was filed in this office

Form R6-7100-57 (9/66)