USDA-FOREST SERVICE GP0 940-	117 3 <i>8</i>
Index File No. E-23 T 5 S P 30 E	CORNER RECORD (SEARCH) Tract or Cor. (Ref. FSM 7151.4) Survey No No  R.D. Ukiah County Umatilla
- Williamotte	N.F. Umatilla State Oregon
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND
Sec	Brass Cap! see Monumentation File,
	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
6	Possible B.T 28" PP with blaze on NW face, scribing faintly visible. FS location poster 458 on tree dated 8/21/69. Doc Cambers. FS metal boundary sign on S. side of tree.
PHOTO IDENTIFICATION DATA	
Photo No	
Filed At.	3
Object Ident	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
Ident. By	Followed blazes N to New Western Route Road and put up
PLANE COORDINATE POSITION DATA	location poster 54-5.
State Zone X Y	
Estab. By	
Signature B <sub>.</sub> Moore	Title Division Headquarters Date 7100-52 (3/68) Eng. Tech. Umatilla \$,0, 8/73

				R ŘECORD (1					
MONUMENT: DESC	RIBE NEW MONUN	MENT SET, O	R WORK DON	TO PRESERVE	EXISTING	MONUMENT			
CCESSORIES : D	ESCRIBE NEW BT	S WITNESS	OBJECTS ETC.	ESTABLISHED	OR WORK	DONE TO PRESER	VE EXISTIN	IG EVIDENCE	:
									1
									:
	•								
	4			*					
	<u>*</u>								
Nork Done By		Title		Dat	·	State Registrat	ion No.		
Certified Cor. Reco	rd Prepared ? Y	es No	Filed At:	·			Date		
			RE	MARKS					

Index File No. E-2 3 T. R. M. Tract or Surv. No. Cor. 13

يز