CERTIFIED RECORD OF LAND CORNER MONUMENTATION

6-8

History of original corner establishment: Corner not previously established. DIAGRAM T5S R30E C <u>E 1/1</u>6 C S8 1980 PLS 848

Description of corner evidence found:

N.A.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 3"x30" galv iron pipe with 3" brass cap. 20" in the ground & raised a mound of stone around pipe. Stamped brass cap as shown in the diagram. From Which:

A pine 14" dia. bears N 13 W 74.7 ft. scribed C E 1/16 S8 BT. A pine 9" dia bears S 30 30' W 33.5 ft. " " " " "

Nailed brass washers stamped PLS 848 & bearing tree signs to each tree painted red band around each tree.

Set steel posts with warning & bdry. signs 8'S & 7'W.

Bearing solar grid.

REGISTERED PROFESSIONAL LAND SURVEYOR

DOUGLAS M. FERGUSON

Witness to above corner.

L. Wyllie

Office of Surveyor County of Umatilla State of Orsgan I hereby certify that the within instrument was filed in this office for record on the 26 day of Uanuary 198!	G.8
(COUNTY OFFICIAL) (DEPUTY)	

Form R6-7100-57 (9/71)

☆ GPO-798-276