CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Corner established in 1883 by F. W. Campbell under General Land Office Contract No. 468.

Surveyor General Record states:

Set basalt stone 16"x10"x9", marked 1 on North face, from which:

A 8" Pine bears S9W, 48 1ks. A 10" Pine bears N79W, 76 1ks. DIAGRAM T58 R30E 8 9 **S16** t Corner

No record of subsequent remonumentation was found in County Records. Description of corner evidence found: Found stone, call size in mound of stone marked 4, from which:

Original BTs

A dead and down Lodge Pole Pine bears S9W, 31.7 ft., scribes visable.

The remains of a dead and down Lodge Pole Pine stump bears S79W, 50.2 ft., no scribing visable.

Description of monument and accessories I established to perpetuate the original location of this corner

In position of stone, I set 21 x30" pipe with brass cap marked as shown, 24" in ground, from which:

New BTs.

A 14" Pine bears N61°E, 127.6 ft. marked \$59 T5S R30E BT.

A 14" Lodge Pole Pine bears S5°W, 32.4 ft. marked \$516 T5S R30E BT.

Nailed brass washer to BT blazes.

Set steel fence post 5±ft. North of corner.

Buried original corner stone South and along side pipe.

Measurements taken to center of new BTs.

Corner is N20°W, 50 ft. from a small stock water pond.

Used steel tape and magnetic compass with 20°E declination.

T5S R30E S 9 **S16** 1974 PLS 644

REGISTERED PROFESSIONAL

LAND SURVEYOR

OREGON JULY 10, 1914 DUANE I. GRIFFITH 644