CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Corner established in 1883 by F. W. Campbell under General Land Office Contract No. 468.

Surveyor General Record States:

Set post for cor. to sect's, 11-12-13-14. From which:

A 30" Pine bears S 38 E, 10 1ks. A 20" Pine bears N 69 W, 53 lks. A 30" Pine bears S 18 W, 83 lks.

Dug pit 18 x 18 x 12 and raised mound of earth.

DIAGRAM T.5 S R.30 E. S 11 S 12 S 14 S 13

No record of subsequent remonumentation was found in County Records. Description of corner evidence found: Found 2 original BTs as follows:

A 24" Pine, poor condition, bears S37E, 6.6 ft., scribes visable.

A 30" Pine, good condition, bears S16W, 54.8 ft., scribes visable.

No evidence of other BT or original stake found.

Description of monument and accessories I established to perpetuate the original location of this corner

At corner point, based on original BTs, I set $2\frac{1}{2}$ "x30" iron pipe with brass cap, marked as shown, 24" in ground, from which:

New BTs

A 10" Pine bears N28E, 12.2 ft. marked T5S R30E S12 BT. A 8" Pine bears S13E, 57.7 ft. marked T5S R30E S13 BT. A 18" Pine bears N36W, 77.1 ft. marked T5S R30E S11 BT.

Nailed brass washer to BT blaze.

Set steel fence post 5± ft. North of corner, Used steel tape and magnetic compass with 20 E declination.

Measured to face of blaze on original BTs and center of new BTs.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON DUANE I. GRIFFITH

J-22 R

T 5S R 30E

S 11 S 12

S 14 S 13 1974 PLS 644