USDA-FOREST SERVICE GPO 94	0-117
Index File No. <u>L-5</u>	CORNER RECORD (SEARCH) Tract or Cor. (Ref. FSM 7151.4) Survey No No.
T <u>5S</u> R. <u>30E</u>	R.D. <u>Ukiah</u> County No No
MeridW.M.	N.F. Umatilla State Oregon
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND
Sec 18	Found a stone 13x10x10, marked 1/4. Stone is 10" above ground in fair condition. Monumented By BLM in 1978
/* `	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
	Pine snag 25' tall 26" in DBH has 1/4 S scribed on it. Snag bears N 87° E, 105 1ks. Found stump of other bearing tree, bearing N 10° W, 147 1ks. from corner.
PHOTO IDENTIFICATION DATA	3 3
Photo No.	
Filed At.	
Object Ident	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
Ident. By	TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
Signature 7	
PLANE COORDINATE POSITION DATA	
State Zone	
X	
Y	
Estob. By	
Signature M. L. Christain	Title Division Headquarters Date 7100-52 (3/68)
	5

	(PERPETUATION)

DESCRIBE NEW MONUMEN			

ACCESSORIES : DESCRIBE NEW BTIS WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE Painted stone red and drove a steel post 4' east of stone with two attention signs attached. Painted snag with 6" red band with proper signs attached. Painted what was left of scribing on stump of other bearing tree and attached a metal sign to the top of stump.

	4 .					10
Work Done By	Til	le	Date	State Registration No.	er de la rec	
Certified Cor. Record Prepare	d ? Yes I	No Filed At:	*	Date_		. 11
			PEMARKS		٦	

Index File No. R. Tract or Surv. No. Cor. Τ. M.