	2
Index File No. <u>N-9</u>	CORNER RECORD (SEARCH) Tract-or Cor. Survey No No
T <u>5 S.</u> R. <u>30 E.</u>	R.D. <u>Ukiah</u> County <u>Umatilla</u>
Merid. <u>Willamette</u>	N.F. <u>Umatilla</u> State <u>Oregon</u>
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND
Sec.	Scattered rubble gives some evidence of corner location.  Monumented by BLM, 1978
16	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND A 12" pine, down & rotting, bears N. 78°E., approx. 31 links, scribed T5S, R30E, S16, B.T. A 34" pine, down & rotting, bears S. 29° E., approx. 30 links. No scribing visible; should be on
PHOTO IDENTIFICATION DATA Photo No Filed At	side against ground. A 32" pine, down & rotting, bears S. 730 W., approx. 14 links. Scribed T5S., R.30E., S20, B.T. Some evidence of pine stump bears N. 850 W. approx. 48 lks. Down tree comp. rotted.
Object Ident.	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
Ident. By Signature	From New Western Route Rd., travel southerly on Road S-420 for
PLANE COORDINATE POSITION DATA	Zabout 1.9 miles to a point about 1000' N. of Sec. line between Sec. 9 & 16. Turn west on logging road which meanders W. and S.
State Zone	Travel about 1.9 miles to road forks. (I placed 2 location poster
x	on approx. section line at this point, 1 for 4 corner East and 1
Y	for sec. corner W. Follow ribbons E. to 4 cor., approx. 1200' W.
Estab. By	to sec. corner approx. 1400'. (Dist. on location posters - est <sub>4</sub> )
Signature	Title Division Headquarters Date 7100-52
J.G. Hollamon.	Engr. Tech Umatilla N.F S.O. 9-19-73 REV. 65 5

n	RNFR	RECORD	PERPET	(NOITAUT
ソレ	UNEU	NECOND	LPENTE	UMITON

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

I placed B.T. tags on the two B.T.'s not having one and painted a red ring around all three. I hung red and white striped ribbon along south line of Section 16 (meandering) from Road S-420 west to section corner. (16-17-20-21)

				•			10
Work Done By		_ Title _		Dote	State Registration No.	11.	
Certified Cor. Record Prepared	? Yes	No	Filed At:		Date		
•			DEMARK	· c		<u> </u>	

Location about one-third down steep, west facing slope. Probably satisfactory for monumentation.

Some strips of white plastic in vicinity probably indicated corner has been aerial photoed.

Location poster on 18" Douglas-fir about 20' N.E. of corner area.

12 Index File No. № 9 T. R. M. Tract or Surv. No. Cor, 13

ndex File No. N-9	CORNER RECORD (SEARCH) Tract or Cor. Survey No No
1 <u>5 5.</u> R. <u>30 E.</u>	R.D. UKIAH County Umatilla
Merid بنال	N.F. Umatilla State ORC.
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND
16	Monumented By BLM, 1978
	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
	10" O.B.H. Lodge Pole Pine, dead And down
	30" D.B.H. PONd. Pine, dead AND down
6	30" D.B. H. Pond. Pine, dead and down
PHOTO IDENTIFICATION DATA	30 D.D. H. TONG. PINE, BEAD AND DOWN
Photo No Filed At.	20" Piñe Stump.
Object ident.	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
dent. By	
LANE COORDINATE POSITION DATA	
State Zone	
X	
Estab. By	
Signature	Title Division Headquarters Date 7100-52
DON MCCUllough	FORESTRY Tech. UKIAH 9-15-66 REV. 65 5

00000			
CORNER	RECORD	(PERPETUATION)	۱

MONUMENT: DESCRIBE				

	Park Services	• *					+ 49	
ACCECCODIEC	DECCRIBE NEW	DTI- MITNESS	20 15070 570	50710110115			· ·	9
ACCESSORIES	DESCRIBE NEW	BI'S WIINESS	DBJECIS EIC.	. ESTABLISHEL	, or work	DONE TO PRESERVE EXI	STING EVIDENCE	
-								
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1							
							,	10
Work Done By		Title		Do	te	State Registration No or Agency		_
Certified Cor. R	ecord Prepared	? Yes No	Filed At:			Date		11

REMARKS

Index File No. N- 9 T. R. M. Tract or Surv. No. Cor. 13