History of original corner establishment:

No previous history

DIAGRAM
Cap Stamped
T 5 S
C 1/4
S 9
R 34 E
1978
ORLS 645

Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner:

I set a  $2\frac{1}{2}$ " brass cap on a 30" galv. iron pipe, and stamped as shown above, in the ground, and placed a large mound of stone around the monument.

New bearing trees: A pine 9" dia. bears N 56 W, 58.46 feet scribed  $\frac{1}{4}$ S S9 BT. A pine 8" dia. bears S 40 E, 36.11 feet scribed  $\frac{1}{4}$ S S9 BT.

PROFESSIONAL
LAND SURVEYOR

Pames HHam Homes
8-21-78

OREGON JULY 10, 1964 JAMES H. HAMBLETON 645 I hereby certify the above corner monument was re-established as herein described in August 1978.

Witnesses

Crew Chief

6-1

Form R6-7100-57 (9/71)

☆ GPO-798-276

93-39-B