Index File No.

History of original corner establishment:

The original corner was set by J. Cooper under Contract No. 397, approved April 5, 1882. He set two bearing trees: a 10" Pine bearing N36°W, 80 lks. and a 27" Pine bearing N50°E, 30 lks.

DIAGRAM T5S 1/4 33 1/2E, R34E 13

Description of corner evidence found:

Found 3.5" BLM brass cap rising 14" on 2.5" iron pipe. Cap is stamped:

Bearing trees found:

A 13" P. Pine bears S73°E, 34.0 ft., scribed (1/4 S18 BT). A 16" P. Pine bears N18°W, 52.8 ft. scribed (1/4 S) healed over.

T5S 1/4 R33 1/2E|R34E

1977

Description of monument and accessories I established to perpetuate the original location of this corner:

Raised rock mound around cap. Set steel fence post 4.0 ft. north.

Brass LS 1844 disc in lower end of blaze. Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982.

Compass Declination: 19 3/4°E

Witness: Duane Scott

Corner is found 100 ft. east of dirt tract in clearing, reached from end of Road 5160-361.

I hereby certify the above described corner monument and/or accessories was established in June of 1984.

> REGISTERED PROFESSIONAL LAND SURVEYOR OREGON

DAVID E. SCOTT 1844

Office of County of State of....... I hereby certify that the within instrument was filed in this office for record on the...... day of....... , 19..... by (COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

93-39-B

₩ GPO--798-276