USDA-FOREST SERVICE	
Index File NoL-7	CORNER RECORD (SEARCH) Tract or Cor.  (Ref. FSM 7151.4) Survey No. No.
7 <u>5 S</u> R. <u>34 E</u>	R.D. La Grande County Union
Merid. <u>Willamette</u>	N.F.Wallow-Whitman State Oregon
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND
T 5 S R 34 E C 1/4 S 17	None. Corner established as part of this survey  DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
PLS 1106	None.
PHOTO IDENTIFICATION DATA	
Photo No Filed At.	
Object Ident	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
PLANE COORDINATE POSITION DATA	Corner is 500' West of Road No. 5160.
State Zone       X       Y       Estab. By       Agency 8	4
Will. R. Wali	Title Division Headquarters Date FS-7100-52 (3/68) Land Surveyor Pendleton, OR. 10-28-93

## CORNER RECORD (PERPETUATION)

MONUMENT DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT At position established by survey... Set a  $2\frac{1}{2}$ " aluminum cap on  $2\frac{1}{2}$ "x30" aluminum pipe 28" in ground surrounded with mound of earth & stone . Set steel fence post of corner & attached sign 54-9 & 54-2. Compass declination 180 East.

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE New bearing trees established:

A 19"diam. Western Earch brs. S80°E, 135.9' scribed C1/4S17 BT. A 12"diam douglas fir brs  $\S15^{\circ}$ W,58.0' scribed Cl/4S17 BT.

A 81 diam. Western Larch brs. N84 W,48.0' scribed C1/4S17 BT.

A 10"diam.Western Larch brs. N46°W, 47.1' scribed C1/4S17 BT.

New bearing trees have a brass washer stamped PLS 1106 nailed to face of blaze. Attached sign 54-3 & 54-9, painted face of blaze &

a 6" red band around each BT.

Work Done By. W.R.Wells Title Land Surveyor Date 10-28-93 State Registration No. PLS 1106

Certified Cor. Record Prepared ? Yes XXXXX Filed AtUnatilla County Surveyor Date

REMARKS

Cor.

Tract or Surv. No.