## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Corner was originally established by Rufus S. Moore, U.S. Deputy Surveyor, under Contract No. 451, dated June 12, 1882. Surveyor General records state: Set a post 3 ft. long 3 ins. sq. 24 ins. in ground for 4 sec. cor. marked 4S on W. face. from which: A tamarack 20 ins. in dia. bears N 19° W 62 lks dist. marked 4 S BT. A fir 24 ins. in dia. bears S 45° W 26 lks dist. 4 S BT.

N-3DIAGRAM T5S R34E S18 1/4----S19 1993 PLS 1106

## Description of corner evidence found:

None. Corner re-established by single proportionate method between the Northwest corner and Northeast corner of Section 19.

This corner was searched for by a 2 person crew on 3 separate occasions for a total 6 hours. 3 1/2 hours of professional land surveyor time was spent searching. A search radius of 250 feet was covered. The area has been logged and burnt. Topographic call to the spring branch East of corner fits the calculated corner position.

## Description of monument and accessories I established to perpetuate the original location of this corner:

At position determined by survey...

Set a  $2\frac{1}{2}$ "X30" aluminum pipe with  $2\frac{1}{2}$ " aluminum cap, 26" in ground and surrounded with a mound of stone to cap, marked as shown in corner diagram.

Attached sign 54-9 to steel fence post, set 4.0 feet East of monument.

New bearing trees established:

A  $9\frac{1}{2}$ " white fir bears N 66° E - 58.9 feet, scribed: 1/4S18 BT.

A 23" ponderosa pine bears S 01° W - 86.3 feet, scribed: 1/4S19 BT. A 10" western larch bears S 66° W - 66.7 feet, scribed: 1/4S19 BT.

A 20" white fir bears N  $22\frac{1}{2}$ ° E - 94.3 feet, scribed: 1/4S18 BT.

New bearing trees have a brass washer stamped 'PLS 1106' nailed to face of blaze. Attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each bearing tree. REGISTERED

I hereby certify that the above corner was properly re-established to U.S.F.S standards by me on October 22,1993.

Compass declination 18° East.

LAND SURVEYOR Will- R. Wells OREGON JULY 22, 1977 WILLIAM R. WELLS 1106

PROFESSIONAL

Office of County Su	rveyor	County of	Umatilla	renews	12-31-94
State ofOr.egon					
for record on the day o	of	, 19.			
	by				
(COUNTY OFFIC	IAL) -		(DEPUTY)		

Form R6-7100-57 (9/71)

RECEIVED BY

\*GPO-591-971, 1988

Umatilla County Surveyor