File No. N-3	CORNER RECORD (SEARCH) Tract or Corly Confe
T <u>5 S</u> R. <u>.34 E</u>	R.D. LA GRANDE County UMATILLA Cor. 14518
Merid. <u>WM</u>	
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND
75S R34E	TOUND FOUND
1 70 7046	
	NONE NONE
518	
	DESCRIBE REARING TREES OR OTHER
519	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
017	NONE
	NONE
	6
PHOTO IDENTIFICATION DATA	
hoto No.	
iled At.	
Object Identdent. By	DESCRIBE CORNER LOCATION RELATIVE TO MEAD BY
Signature	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
LANE COORDINATE POSITION DATA	
tate Zone	TSS R331/2 and SECTIONS 18 \$ 19 T55 R34E
	- FOUND NO FILLDE LOS
adah D.	FOUND NO EVIDENCE OF MONUMENT OR
stab. By	
EARL E, STRANG	8 HEAVILY LOGGER OVER. Title Division Headquarters 4

CODNED	PECORD (PERPETUATION)
CORNER	RECORD	

TO THE TAX	
MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT	
도둑하는 보고 있는 경우 마다 마다 무슨 사람이 되었다. 그는	9
ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE	
	10
State Registration No. Wark Done By Title Date or Agency	
30000	
Certified Cor. Record Prepared ? Yes No Filed At: Date	
TRONG TO THE TRANSPORT OF THE TRANSPOR	

Index File No. NJ3 T. 55 R. 346 M. WM Tract or Surv. No.

1/4 Cor. OF SECT. 18 \$ 19

USDA-FOREST SERVICE	CORNER RECORD (SEARCH) Tract or	6			
File No. N 3	(Ref. FSM 7151.4) Survey No.	Cor. No.			
T _{5S} R. 34E	R.D. LaCrande County _{Umatilla}				
Merid.Willamette	_ N.F. Wallowa Whitmarstote Oregon				
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND				
T5S R34E	None. Re-established corner by single programmer had				
A	measurement between the NW & NE corners	roportion			
S18	a NE corners	of Section 1			
1/4					
N S19		aya marana ay a sanara da sana Sanara da sanara da			
1993	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND				
PLS 1106					
to the second se	None.				
PHOTO IDENTIFICATION DATA					
Photo No.					
Filed At.					
Object Ident.	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HO	W TO REACH CORNER			
Ident. By Signature					
PLANE COORDINATE POSITION DATA					
	Corner is on East slope in an old logged				
StateZone	approximately 150 feet East of Road No.	area			
X ————————————————————————————————————	360.	5160-			
Estob. By					
Agency	- I				

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT Set $2\frac{1}{2}$ " aluminum cap on $2\frac{1}{2}$ "X30" aluminum pipe, 26" in ground with mound of earth and stone to cap, marked as shown in corner diagram. Attached sign 54-9 to steel fence post, set 4.0 feet East of monument.

andre de Companya de la companya de A la companya de la c	***
ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE A $9\frac{1}{2}$ " white fir bears N66°E-58.9 feet, scribed: 1/4S18 BT. A 23" ponderosa pine bears S01°W-86.3 feet, scribed: 1/4S19 BT. A 10" western larch bears S66°W-66.7 feet, scribed: 1/4S19 BT. A 20" white fir bears N22 $\frac{1}{2}$ °E-94.3 feet, scribed: 1/4S18 BT. Bearing trees have brass washer stamped 'PLS 1106' nailed to the face of the blaze, attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each bearing tree.	f
Work Done By. WR Wells Title PLS Date State Registration No. PLS 1106 Certified Cor. Record Prepared ? Yes No Filed At: Date	