USBA-FOREST SERVICE Index File No. N-5 T 5 S R. 34 S	R.D. La Grande County Union Cor.
Merio. WIII allecte	N.F.Wallowa-Whitman State Oregon
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND
T 5 S R 34 E	No trace of corner post in area of previous heavy logging.
S 18 S 17	
N S 19 S 20	
1993	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
PLS 1106	A 16" western larch stump bears N12°E, 20 1ks (13.2') with blaze and axe marks visible scribing burns and
PHOTO IDENTIFICATION DATA	A stump hole bears S35°E, 9 lks (5.9') with pieces of rotted blaze alongside.
Photo No	
Object Ident.	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
Ident. By	CONTRACTOR RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
Signature 7	Corner is approx. 125' - 150' West of Road 5160-340.
PLANE COORDINATE POSITION DATA	Corner is visible from cut bank West of Road.
State Zone	way in the same of the same with the same with the same of the sam
>	
Estob. By	
Will-R. Wells	Title Division Headquarters Date FS-7100-52 (3/68) Land Surveyor Pendleton, OR. 10-26-93

CORNER RECORD (PERPETUATION)

A VARIABLE OF THE CORNER RECORD (PERPETOATION)	-
MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT At position established by record bearing and distance from recovered remnants of Section 17 bearing tree Set a $2\frac{1}{2}$ " aluminum cap on $2\frac{1}{2}$ "x30" aluminum pipe 27" in ground surrounded with mound of earth and stone. Set a fence post next to corner and attached sign 54-9 and 54-2. Compass declination 18 East.	3
ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE New bearing trees established: A $7\frac{1}{2}$ " diam.western larch brs. N12°E,98.3' scribed T5SR34ES17 BT. A 9" diam.alpine fir brs S30°E,51.8' scribed T5SR34ES20 BT. A $13\frac{1}{2}$ "diam.alpine fir brs S33°W,76.4' scribed T5SR34ES19 BT. A 7" diam.alpine fir brs N68°W,88.3' scribed T5SR34ES18 BT. New bearing trees have a brass washer stamped PLS 1106 nailed to face of blaze. Attached sign 54-3 & 54-9, painted face of blaze &	10
Work Done By. W.R.Wells Title Land Surveyor Dotal Dotal Pls 1106 Certified Cor. Record Prepared ? Yes XXXX Filed Almatilla County Surveyor Date 8 94	l i
a 6" red band around each BT.	

12 13

R. 34 E

WM. Tract or Surv. No. GPO: 1986 0 - 439-095

Cor.

USDA-FOREST SERVICE Index File No	CORNER RECORD (S	SEARCH)	Tract or	Cor. 19 20
T <u>55</u> R. <u>34E</u>			Survey No	
Merid W ILL.		County <u>///</u> State	MATTLL DRE.	7
ORNER DIAGRAM	DESCRIBE CORNER MONUMENT			
18 17				
19 20	DESCRIBE BEARING TREES OR ("Thone I Heavy and wad word,	Commin	u mes	the past 10 yrs, through location, one about 12" or least
HOTO IDENTIFICATION DATA hoto No iled At.	Tota of w, L, sturn	ps in a	va all.	ore about 12" or leasta
Object Identdent. By	DESCRIBE CORNER LOCATION RE	LATIVE TO N	EAR-BY FEATU	PRES, ALSO HOW TO REACH CORNER
LANE COORDINATE POSITION DATA State Zone ((Estab. By				
Agency Signature Dablet	Title Division	/ Headqu	arters	Dote FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)	
MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT	
	9
ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE	
	10

	<u></u>				10
Work Done By.	1.55%	Title	Do	State Registration No. e or Agency	
Certified Cor. Record Prepare	d? Yes	No Filed	At:	Date	11
A STATE OF THE STA			REMARKS		

REMARKS

					12
Index File No.	 R.	Μ,	Tract or Surv. No.	Cor.	13