USDA-FOREST SERVICE	
Index File No. N-7 T 5 S R. 34 E	CORNER RECORD (SEARCH) Tract or Cor. (Ref. FSM 7151.4) Survey No. No. R.D. La Grande County Union N.F.Wallow-Whitman State Oregon
Merid. Willamette	_ N.F.Wallow-Whitman State Oregon
CORNER DIAGRAM T5S R34E	No trace of corner post or bearing trees recovered.
$\frac{1}{4}$ $\frac{\text{S } 17}{\text{S } 20}$	This corner was previously searched on 8-28-84 by Dave Dahlstrom, U.S.F.S. staff, and his search record states the area had been burned 80 to 100 years ago. He found no trace of corner or accessories. DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
PLS 1106	This corner was searched for a total of 5 hours on 3 separate occasions with a 2 person crew. 2 hours of professional land surveyor time was spent. A search
PHOTO IDENTIFICATION DATA Photo No. Filed At.	radius of 150 feet was covered. The corner area burnt many years ago and has been clearcut.
Object Ident	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
PLANE COORDINATE POSITION DATA State Zone X	Corner is on slight North slope in lodgepole pine and tamarack thicket approx. 800' West of Road No. 5169.
Estab. By	- - - 8
Willia Kulels	Title Division Headquarters Date FS-7100-52 (3/68) Land Surveyor Pendleton, OR. 10-27-93

CORNER RECORD (PERPETUATION)

MONUMENT DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT At position determined by single proportionate measurement between the recovered Northwest corner and the existing Northeast corner to Section 17... Set a $2\frac{1}{2}$ " aluminum cap on $2\frac{1}{2}$ "x30" aluminum pipe 26" in ground surrounded with mound of earth only aSet steel fence post next to corner & attached sign 54-9 & 54-2. ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE New bearing trees established: A 16"diam. Western larch brs. N3 W, 88.5' mkd 1/4S17 BT. A 12"diam. Western larch brs. N76 E, 52.2' mkd 1/4S17 BT. A 13"diam. Western larch brs. South 31.6' mkd 1/4S20 BT. A 11½"diam.Western larch brs. S33°W,32.4' mkd 1/4S20 BT. New bearing trees have a brass washer stamped PLS 1106 nailed to face of blaze. Attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each BT. Date 10-27-93 State Registration No. PLS 1106 Work Done By W.R.Wells Title Land Surveyor Certified Cor. Record Prepared ? Yes XXXXX Filed AtUnatilla County Surveyor REMARKS Compass declination 18° East.

> 12 13

Tract or Surv. No.

R. 34 F

WM M.

T.5 S

Index File No. N-7

USDA-FOREST SERVICE	3/2
Index File No	CORNER RECORD (SEARCH) Tract or Cor. /7
T R	R.D. LA GRANDE County UNATILLA
Merid. WILL.	N.F. W-W State ORE,
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND
	Hone,
17	
1 0	
1 20	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
	None area appears to have been burned about
l	100 he was applan to have veen vilined sevous
6	80-100 years doo, Todgepole has come back and died and there has been a mechanical empling rontract
PHOTO IDENTIFICATION DATA	
Photo No.	through the awa.
Filed At.	
Object Ident.	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
Ident. By	
S/gnature 7	
PLANE COORDINATE POSITION DATA	
State Zone	
×	
Υ	
Estab. By	
Signature	Title Division Headquarters Date 50.7400.50.4000
Pave Pahlo	twom CET Fabrarde S-28-84 FS-7100-52 (3/68)

:0	RNER	RECORD (PERPETUATION)
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	11500110 1	

MONUMENT: DESCRIBE	NEW MONUMENT	SET, OR WORK	DONE TO PRESERVE	EXISTING MONUMENT	

ACCESSORIES | DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor. 13

GPO: 1982 O-382-659