CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner originally established by Rufus S Moore, U.S. Deputy Surveyor, under GLO Contract No. 451, dated June 12, 1882.

Surveyor General records state:

Set a post 4 ft. long 4 ins. sq. 24 ins. in ground for Cor. to Secs. 29,30,31 & 32, 300 ft. below 1/4 Sec.Cor. marked T5S S29 on NE, R34ES30 on NW, S31 on SW and

V-5 DIAGRAM T 5 S R 34 E S 29 S 30 S 31 S 32 1106

S32 on SE faces with 1 notch on S and 5 notches on E edges from which:

A pine 4 ins. in dia. bears N33°E,6 lks dist marked T5SR34ES29 BT. A pine 5 ins. in dia. bears N49°W,11 lks dist marked T5SR34ES30 BT. A fir 5 ins. in dia. bears S58°E,34 lks dist marked T5SR34ES32 BT. A fir 14 ins. in dia. bears S20°W,52 lks dist marked T5SR34ES31 BT.

Description of corner evidence found:

Found rotten remains of original wood post below ground surface from which ...

Remains of Section 31 BT, a uprooted 14" diam.fir with visible scribe marks on upper portion of double blaze, brs S20°W,34.3'(52 lks). Remains of Section 32 BT, a uprooted and decaying fir 5" diam. With healed blaze brs S58 E, 22.4'(34 lks).

Description of monument and accessories I established to perpetuate the original location of this corner

At position of recovered original wood post...

Set a $2\frac{1}{2}$ " aluminum cap on $2\frac{1}{2}$ "x30" aluminum pipe 26 " in ground surrounded with mound of earth & stone. Set steel fence post 4' South of corner & attached sign 54-9 & 54-2.

New bearing trees established: A 13"diam.Western larch brs. N1 E 93.0' mkd T5SR34ES29 BT. A 18" diam.White fir brs S52 E ,87.1' mkd T5SR34ES32 BT. A 10" diam.lodgepole pine brs S51 W ,43.9' mkd T5SR34ES31 BT. A $5\frac{1}{2}$ " diam.lodgepole pine brs N78 W ,44.3' mkd T5SR34ES30 BT.

New bearing trees have a brass washer stamped PLS 1106 nailed to face of blaze. Attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each bearing tree. REGISTERED

Compass declination 18° East.

I hereby certify that the above corner was properly re-monumented to U.S.F.S. standards by me on October 27, 1993.

PROFESSIONAL LAND SURVEYOR

Villa- R. Wells OREGON JULY 22, 1977 WILLIAM R. WELLS

1106 renews 12-31-94

Office of County Surveyor County of Umatilla State of Oregon , I hereby certify that the within instrument was filed in this office for record on the day of; 19......, at....... o'clockm., (signed)

RECEIVED BY

Umatilla County Surveyo

Form R6-7100-57 (9/66)