History of original corner establishment: Original survey by Meldrum and Campbell, Contract No. 380, 1881: Set a Pine post for Cor. to Sec.s 5, 6, 31, 32 from which a Fir 7 in. in diam. bears N31°E 50 lks. dist. Fir 16" in diam. bears N17°W 21 lks. dist. Fir 16" in diam. bears S67°W 32 lks. dist. Fir 30" in diam. bears S45°E 40 lks. dist. Remonumentation of corner position from original evidence by

DIAGRAM T6S 32 **R31E** 5 6 **T7S**

PLS 848

Douglas M. Ferguson, LS 848, filed with Grant County Surveyor Nov. 16, 1972.

Found a 16 in. Fir, live in good condition, with scribing visible, bearing N310E, 30.6 ft. from corner position. Found a 36 in. Fir snag with scribing faintly visible bearing S450E, 26.4 ft. from corner position. Found a 36 in. Fir, live in good condition, with grown-over blazes bearing S670W, 21.1 ft. dist. from the corner. (Continued on Page 2 of 2)

At the corner point, we find a 2 1/2" Iron Pipe, extending 6 inches above ground, with brass cap attached, marked: T6S R31E From Which: The remaining 1881 original BT's:
A Fir snag with partial scribing visible on an unhealed blaze S31 | S32 S6 S5 T75 1972

bears N21 $^{\rm OE}$ 31.5 ft. The original N.W. BT is gone. A 30" Grand Fir alive and well-healed bears S67 $^{\rm OW}$ 22.0, and a 30" Fir, now a rotten and shattered stob, bears S45°E 26.4 ft. Bearing trees established in 1972 by Ferguson:

A 32" Grand Fir, alive and healed, bears N17°W 19.4 ft., and a 10" Grand Fir, alive and healed, bears S40°E 44.9 ft.

Description of monument and accessories I established to perpetuate the original location of this corner:

We mark a new bearing tree:

A 10" Grand Fir, scribed "T6S R31E S32 BT" on a double blaze bears N82°E 42.9 ft., with brass washer marked "LS 1099" nailed to face of lower blaze.

Corner located 55' West of a Creek, course North, and 10' South of an E-W fence.

Magnetic Compass (Declination 190 East)

Steel Tape

August 26, 1982

Witnesses:

Gary Langlitz Jeff Anderson Greg Orton

REGISTERED **PROFESSIONAL** AND SURVEYOR OREGON . LANGLITZ

Office of Surveyor County of Umatilla dey of ... January 1983

Form R6-7100-57 (9/71)

RECEIVED BY Umatilla County Surveyor Date Rec'd by No. 83-03-8

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishm Set a 30 in. x 2½ in. iron as shown, 25 in. in the gro 5 & 6, from which new BT's A Fir 36 in. diam. bears R31E, S31 BT.	pipe with 3 in. brass and for the corner to N17 ⁰ W, 19.4 ft. dist	Secs. 31, 32, . marked T6S,	DIAGRAM
A Fir 9 in. diam. bears R31E, S5 BT.			
Distances taken to a bra of each tree.	ss washer in the blaze	T.6S R.31E.	
Used steel tape and magn declination = 20°E.	etic compass with	S3 <u>1 S</u> 32 S6 S5 T7S.	
		1972 PLS 848	
Description of corner evidence found	l:		
			6 2
		A . 50	
Description of monument and accessoriginal location of this corner:	ories I established to perpetua	ate the	
		70 700	
		5 9 3	
			44
			£3
	₩		
1 KS	* * .		
			5 III
Office of Survey or	County of	matilla	
Nanyl A Xil	hereby certify that the within ind anuary 19.83 comblem by Selly	Strument was filed in this	office V5
(COUNTY OFFICIAL)	7	(DEPUTY)	RECEIVED BY
orm R6-7100-57 (9/71)			illa County Surveyor
a como 45% Metaliffa			
		Date	
	- 10 M	Rec	83-03-B
		1.0	0000