CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original comer establishment:

U.S. Cadastral Surveyors, under special instructions Group Numbers 350 and 643, set a 2½"X 30" irom post with a brass cap marked:

monument 24" in the ground, from which:

E1/16 <u>\$24</u> \$25 1968 T63 R32E E11/16 S24 E25

R-24

DIAGRAM

A Fir, 18" dia., N21°E, 36 1ks. A Pine, 10" dia., 842°W, 113 1ks.

Description of corner evidence found:

I found a 21 iron pipe with a brass cap marked: im a mound of stone. From the corner:

E1/16 <u>\$24</u> \$25 1968

A White Fir, 25" dia., N21°E, 23.8 ft., with a healed blaze. A Ponderosa Pine, 13" dia., S472°W, 74.1 ft., with a healed blaze.

Description of monument and accessories I established to perpetuate the

original location of this corner:

I painted the blazes of the BTs and a 6" band around them red and attached new BT tags and "Land Survey Monument" signs. I drove a 6' steel fence post within 5' of the corner and attached a "Land Survey Monument" signs.

Measured to center of BTs using steel tape and staff compass. Magnetic declination set at $20\frac{1}{2}$ E.

Oct. 31, 1986

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Tantle Munro
OREGON
JULY 13, 1979
FAYETTE S. MUNRO
1832

	and the second s
Office of	ounty of
State of / hereby certify that :	the within instrument was filed in this office
for record on the day of	, 19
by	
(COUNTY OFFICIAL)	(DEPUTY)

Form R6-7100-57 (9/71)

RECEIVED BY

Umatilla County Surveyor

Date 12-11-86

No. 86-138-M.

GPO-798-276